


Jan. 29, 1946  
Sept. 5, 1956  
Oct. 30, 1956  
Apr. 2, 1958

TRACK DIAGRAM.  
I.C.R.R.  
AND  
WABASH.R.R. & L.E.&W.R.R.



GIBSON, CITY, ILL.      Office Of Sig Engineer. SD 42 D  
I.C. System. Chicago, Ill.  
Jan. 29, 1946.  
Sept. 5, 1956  
Oct. 30, 1958  
April 29, 1959  
Sept. 4, 1957

MANIPULATION.  
I.C.R.R. WABASH.R.R. & L.E. & W.R.R.

I.C.R.R. NORTH BOUND												I.C.R.R. SOUTH BOUND.															
ROUTE	LEVERS				REVERSED.								ROUTE	LEVERS				REVERSED.									
5 <sub>A</sub> TO 44				17	5								44 TO 5 <sub>A</sub>				17	44									
5 <sub>A</sub> TO 44				17	5	CALL ON				PUSH BUTTON				44 TO 5 <sub>A</sub>				17	44	CALL ON				PUSH BUTTON			
5 <sub>C</sub> TO 44	19	17	5										44 TO 5 <sub>C</sub>	19	17	44											
5 <sub>C</sub> TO 44	19	17	5			CALL ON				PUSH BUTTON				44 TO 5 <sub>C</sub>	19	17	44			CALL ON				PUSH BUTTON			
31 TO 38	12			37	31																						
													46 TO 1	15	16		46										
													38 TO 31	12			37	38									
1 TO 46	15	16			1																						
WABASH.R.R.												L.E. & W.R.R.															
ROUTE	LEVERS				REVERSED.								ROUTE	LEVERS				REVERSED.									
2 TO 39	25	2	NORTH BOUND									9 TO 47	22	9	EAST BOUND												
39 TO 2	25	39	SOUTH BOUND									47 TO 9	22	47	WEST BOUND												