

INDEX

Thirteenth Volume—From January, 1920, to December, 1920

GENERAL INDEX

[Illustrated articles are indicated thus*. Editorials are indicated thus†]

- A**
- Accidents:
- Adamsville, Ala., Butting Collision on the St. Louis-San Francisco 210
 - Alabama & Great Southern, Collision at Trussville, Ala. 433
 - Bulletin No. 73 275
 - Bulletin No. 74 495
 - Butting Collision of Two Pere Marquette Trains on B. & O. near Chicago 291
 - Due to Disregard of Flagging Rules 231
 - Due to the Use of Train Staff System 305
 - Investigations by I. C. C. 278
 - Norfolk & Western at Walton, Va. 144
 - On French Railways 44
 - On New York Central at Erie, Pa. 484
 - On Portland Division of Southern Pacific Near Bertha, Ore. 262
 - Records of Non-Automatic Territory 306
 - Report on Collision at Riverside, Vt. by I. C. C. 290
 - Rules to Prevent Motor and Hand Car 233
 - Ackurate Rubber Company, Inc. 486
 - Action on Moving Conductor in Magnetic Field 255
 - American Association of Engineers:
 - Annual Meeting 136
 - State Position on Trade Unionism 45
 - Air Compressors, National Compressed Air Machinery Co. 284
 - Air Reduction Sales Company 350
 - American Railway Association, Signal Division:
 - Annual Meeting 229, 238-265
 - Annual Report of Signal Section 494
 - Committee VIII—A.C. Automatic Block Signaling 503-517
 - Committee XI—Batteries 323
 - Committee XII—Contracts Report 505
 - Committee II—Mechanical Interlocking 170, 333, 506
 - Committee III—Power Interlocking 165, 330, 514
 - Committee IV—D.C. Automatic Block Signaling 503, 509
 - Committee V—Maintenance Rules and Instructions 313, 503
 - Committee VI—Standard Design 322, 503, 519
 - Committee VII—Direct Current Relays 161, 329, 503
 - Committee IX—Wires and Cables 168, 376, 503
 - Committee X—Signal Practice 321, 506
 - Committee XIII—Electrical Testing 334, 503, 513
 - Committee XV—Valuation 333
 - Committee XVI—Oils 163, 312, 503
 - Committee XVII—Pole Lines 334, 503
 - Committee, New One Formed 179
 - December Stated Meeting 488, 503
 - Electrical Testing 487
 - How Far Should It Consider Standardization? 488
 - Joint Committee on Automatic Train Control 456
 - Limits of Standardization 440
 - Letter to the Editor on "Average Member" 233
 - Letters to the Editor on 306
 - Low Voltage Switch Machine Discussed 50
 - March Meeting 191, 107, 156, 531
 - R. S. A. as a Separate Section 354
 - Second Annual Convention 310, 335
 - Sectional Committee 48, 1396
 - Sectional Committee Meeting Minutes, Letters to the Editor 489
 - Sidelights on 141
 - Signaling Practice 506
 - What Its Work Consists of 354
 - American Railway Association, Signal Division Sectional Committee Meeting:
 - Chicago Section 88, 338, 373, 410, 443, 476
 - Cincinnati 45, 64, 338, 374, 476
 - Kansas City Sectional Meeting 262, 338, 373, 410, 476
 - New York 45, 68, 222, 230, 410, 476, 482
 - St. Louis 114, 115, 153, 300, 338, 356, 410, 476
 - St. Paul 114, 154, 253, 373
 - Savannah, Georgia, Section 476
 - Texas Sectional Committee 222, 373
 - American Railway Association, T. & T. Division:
 - Annual Meeting 353, 374, 1396, 414
 - Committee No. 1—Construction and Maintenance Outside Plant 417
 - Committee No. 2—Construction and Maintenance Inside Plant 423
 - Committee No. 3—Protection Against Electrolysis 424, 527
 - Committee No. 4—Protection Against Lightning, Electric Light and Power Circuits 425
 - Committee No. 5—Telegraph and Telephone Development 425
 - Committee No. 6—Message Traffic 426
 - Committee No. 7—Inductive Interference 429, 468
 - Committee of Direction Report 414
 - New Appointments 467, 534
 - Pole Line Construction 1355
 - Special Committee on Future Activities Report 416
 - Sub-Committee "A"—Construction and Maintenance of Pole Lines 417
 - Sub-Committee "B"—Wire Cross-ling 421
 - Sub-Committee "C"—Underground Construction 422
 - Sub-Committee "D"—Transpositions 423
 - American Railroad Signal Supervisory Association 135
 - Atchison, Topeka & Santa Fe:
 - Interlocking Construction 88, 436
 - Atlantic Coast Line:
 - Interlocking at Richmond, Va. 490
 - Augereau's Wireless Cab Signal 247
 - Automatic Block Signals:
 - Completed in 1919 18
 - Statistics for the Past 15 Years 4
 - Under Construction at End of 1919 18, 26
 - Automatic Train Control:
 - Accomplishments of 448
 - Bill Requiring Roads to Install 29
 - Bourdette-Brookins Device 411
 - Clearance Problem 448
 - Committee Report 30
 - Committee on 448
 - Committee Reported by New York State Public Service Commission 436
 - Conclusions of Committee 35
 - Classification and Character of Train Control Device 83
 - Definition 30
 - Discussed at New York Railroad Club 148-185
 - Discussed by J. Beaumont 151
 - Discussed by Major Ames 149
 - Discussed by W. P. Borland 149
 - Discussion of 451
 - Experimental Installation Requested on New York Central 392
 - Function of 447
 - General Discussion by Committee 34
 - General Discussion of 452
 - General Requisites for 452
 - Government Viewpoint 443
 - Human Agency Failure 449
 - Importance of 1396
 - Importance of During 1919 12
 - Inspection of Casale on Rock Island 175
 - Installation of During 1919 26
 - Installation on the Rock Island 204
 - Installed in the United States Since 1909 18
 - Joint Committee Meeting, November 5 502
 - Joint Committee of A. R. A. 456
 - Letters to the Editor on Committee Report 94
 - Letter to Editor 191, 232, 268
 - Maintenance Problem 449
 - National Safety Appliance 94
 - Necessities for 103
 - Need for 95
 - New Committee on in England 534
 - One Solution of the Problem 451
 - On Victorian Railways, Melbourne, Australia 196
 - Operating Rules Problem 449
 - Outline of Committee's Work 30
 - Paper by H. S. Baillet 148
 - Points to Be Considered 448
 - Plans and Devices Examined by Committee 33
 - Problems Discussed 206
 - Problems of Installation 447
 - Problems of Refinement 447
 - Problems to Date 443
 - Proposed New Construction for 1920 18
 - Provided for in Revised Transportation Act 107
 - Railroad Viewpoint 449
 - Recommendations of Committee 35
 - Regan Device in England 463
 - Requisites for 30
 - Section of Esch Bill 29
 - Some Devices in Service 447
 - Status of 440
 - Tests of Shadle Device 404
 - Train Control Problems 32
 - Why Greater Progress Has Not Been Made 451

B

Ballast:

 - Resistance of in Track Circuit 68

Ballast and Rail:

 - Resistance of in Track Circuit 68

Baltimore & Ohio:

 - Interlocking Construction 137

Battery:

 - Capacity of Cells 42
 - Care of Lead Type Storage Cells 193
 - Cell Tester Instantaneous 182
 - Charging and Cut-off of Storage Cell 118
 - Chemistry of Secondary Cells 79
 - Chemistry of Storage Cell 117
 - Closed Circuit Cells 41
 - Discarding Dry Cells 1353
 - Discharge of Lead Storage Cell 118
 - Electrolyte or Storage Cell 119
 - Formation of Plates for Lead Storage Cells 80
 - General Principles of Lead Storage Type 117
 - Hospital Cases, Storage Cell 119
 - Method of Filling Edison Storage 388
 - Open Circuit Cells 40
 - Putting Lead Cells into Service 81
 - Practical Cells in General 40
 - Questions on Primary Cells 42
 - Questions on Secondary Cells 83
 - Rectifiers for Charging Storage Types 388
 - Report of Committee XI 323
 - Simple Voltaic Cell 38
 - Soda and Gravity on Track Shunts 49
 - Soda and Gravity Used on Track Circuit 49
 - Soda, Operation of 1189
 - Soda, Study of 213
 - Storage Charging by Rectifier 266, 276
 - Study of Primary Types 154
 - Tool for Removing Cover from Storage 483

Bell to Indicate Power Failure 809

Belt Lacing 486

Block Signals:

 - Audible 141
 - Automatic 356
 - Automatic vs. Train Control 268
 - Automatic on Single Track of Southern Pacific 260
 - Completed in 1919 18
 - Installed in the United States Since 1909 18
 - Manual, Controlled Manual, and Automatic, Relative Safety of 274
 - Manual, Controlled Manual, and Automatic, Relative Operating Efficiency of 274
 - Manual Versus Automatic 269
 - Non-Automatic and Accident Records 308
 - Proposed for 1920 18
 - Statistics 267, 280
 - Statistics: Comments on 1304

Block Signaling:

 - Automatic Construction on M. K. & T. 262
 - Progress Made During 1919 12
 - Straight Automatic on Union Pacific 359
 - Statistics from Jan. 1, 1905, to Jan. 1, 1919 6

Block System:

 - What It Is 273

- Bonding Drill:
Chicago Railway Signal & Supply Co., Chicago 138
Bond Wires Welded to Track Circuits 284
Bossard Railway Signal Corporation.. 90
Boston & Albany:
Interlocking Construction 137
Boston Elevated:
Automatic Block Signal Construction 222
Bourdette-Brookings Train Control System 411
Braking Distances:
Method of Computing for Locating Signals 7
Computer 9
Brass:
Bridgeport Brass Co. Distributed Booklet on 264
Brotherhood of Railway Signalmen:
Annual Convention 464
Take Up Matter of Education 139
Building for the Future 1230
- C**
- Cab Signal:
Augereau's Wireless Cab Signal... 247
Cables:
Instructions for Drawing in Paper Insulated Lead Covered 461
Lead Covered: Effect of Electrolysis on 1488
Lead Covered: Protection Against Electrolysis 527
Paper Insulated Lead Cover at Electric Interlocking 458
Report of Committee IX 326
Requisite for Installation of Paper Insulated Lead Covered 460
Specifications for Aerial, Report of Committee IX 326
Specifications for Lead Covered.. 326
Specifications for Making Pothead from Paper Insulated 461
Specification for Paper Insulated Lead Covered 460
Specifications for Rubber Insulated Armored Submarine, Report of Committee IX 326
Specification for Underground Braided 326
Use of and Electric Interlocking.. 1439
Camp Cars:
For Signal Construction Gangs... 1265
Canadian National Railways:
Crossing Protection Construction.. 348, 392
Interlocking Construction 348
Canadian Pacific:
Automatic Block Signal Construction 348
Collision Near Corbell, Ontario... 172
Interlocking Construction 348, 392
Car Interlocking:
Electro-Pneumatic Interlocking Operates Crossing Gate..... 363
Castings, Steel 90
Casale Safety Device Company:
C. A. Lyon Associated with 45
Cell:
Discarding Dry 1253
Lead Type Portable Storage, Specifications for 324
Method of Filling Edison Storage Type 388
Rectifiers for Charging Storage Types 398
Setting Up Soda Type 253
Soda, A Study of in Plain Language 253
Soda, Operation of 1189
Soda, Specifications for, Type "A," Committee X Report 323
Soda, Study of 213
Tool for Removing Cover from Storage 483
Cement, Fire Resisting 260
Central of Brazil:
Electrification of 45
Central Railroad of New Jersey:
Electro-Pneumatic Interlocking Construction 223
Chemical Rectifier, Tests on 292
Chicago, Burlington & Quincy:
Train Operation by Signal Indication on 341
Chicago, Indianapolis & Louisville:
Indianapolis Union Station 145
Interlocking Construction 300
Chicago, Milwaukee & St. Paul:
Electrification on 173
Chicago Pneumatic Tool Company.. 227, 394
Chicago, Rock Island & Pacific:
Telegraph Department Educational Methods 436
Chicago Sectional Meeting:
Considers Automatic Train Control 443
Chicago & Alton:
Automatic Block Signal Construction 436
Chicago & Northwestern:
Collision Near Lambert, Minn... 262
Safety First on 262
Cincinnati, New Orleans & Texas Pacific:
Interlocking Construction 88
Cincinnati, Indianapolis & Western:
Indianapolis Union Station, Telegraph Office 145
Cincinnati Sectional Committee Considers Outlying Switch Control. 499
Circuit Breakers:
Bulletin Issued by Roller Smith Co., N. Y. 227
Circuit Controllers:
Closing Holes in 42
Circuits:
Crossing Bell 134
For Stick Relay on A. P. B. Signals 387
Pole-Changer 134
Release for Detector 388
Resistance of Series Multiple.... 477
Trap Circuit at Electric Railway Crossings 180
Cleveland, Cincinnati, Chicago & St. Louis:
Interlocking at Bellefontaine, Ohio. 110
Interlocking Construction 534
Union Station, Indianapolis, Telegraph Office 145
Cleveland Twist Drill Company... 89, 536
Coding Messages, Modern Brevity Methods 198
Collision:
At Corbell, Ontario 172
At Trussville, Alabama 423
Butting of Two Pere Marquette Trains on B. & O. Near Chicago 291
Chicago & Northwestern, Near Lambert, Minn. 262
Due to the Use of Train Staff System 306
I. C. C. Investigation in Automatic Signal Territory 444
I. C. C. Report on Butting Collision at Adamsville, Ala. 210
On New York Central West of Schenectady 300
On Staff-Operated Line 219
Report of L. C. C. on Accident at Riverside, Vermont 290
Rockledge, Some Lessons to be Learned from 1190
Torpedoes Fail to Prevent Corbell, Walton, Virginia 144
Colorado & Southern:
Despatching Circuits Constructed. 524
Concrete:
Mixing and Handling 154
Conduit:
Placing Wires in 424
Condulets:
Crouse-Hinds Company Issues Bulletin on 438
New Type 362
Confessions of an Ex-Maintainer.. 369
Constitution of the United States... 187
Continuous Rail Crossing Frogs... 90
Copper Clad Steel Company... 227, 394, 535
Crossing:
Continuous Rail, Eymon Type 391
Crossing Gate:
Electric Alarm 457
Operated from Electro-Pneumatic Interlocking Machine 363
Crossings, Highway:
Accidents Had Called Attention to by Public Service Commission, New Hampshire 136
Automatic Flagman for 184
Concrete Posts and Signs for... 421
Michigan Supreme Court Decision. 88
Signal for 184
Southern Pacific Finds Automobile Drivers More Careful in Crossing 45
Wisconsin Railroad Commission Survey of 88
- D**
- "Deadhead," Origin of 259
Detector Circuit for Electric Lock... 386
Direction of Current in Wire Moved in Magnetic Field 255
Drilling Machine:
Portable Type, New Device 533
Duntley Dayton Company, Chicago... 90
- E**
- East Indiana Railway:
Butting Collision on Staff-Operated Line 219
Edison Lamp Works 536
Education:
Application of Ohm's Law for Beginners 126
Brotherhood of Railway Signalmen Take Up Matter of 1296
Electrical Units for the Signal Men Letters to the Editor 441
Methods Proposed by Brotherhood of Signalmen 464
More Means of Obtaining for Signalmen 1265
Of Automobile Drivers Crossing Tracks 8
Of Signalmen to Reduce Failures. 12, 16-122
- Of Signalmen at Sectional Committees 148
Practical Lessons in Electricity for Beginners 176
Practical Lessons in Electricity for Beginners, 215, 255, 380, 478, 522
Practical Lessons for Signalmen... 126
Problems for Solution 11, 38, 79, 1353, 379, 431, 440, 477, 487
Questions for Beginners on Battery Connection, Resistance and Ohm's Law 130
Questions on Primary Cells 42
Questions Pertaining to Magnetism 179
Study of Magnets for Beginners.. 176
Telegraph Matters on C. R. I. & P. Vocational Training 190
Vocational Training for Signalmen What's the Answer?... 379, 431, 477
Electric Interlocking:
Facilities at Richmond, Va., on the A. C. L. 490
Electric Lock:
Specification for on Hand Operated Switches 330
Electric Locks:
Specifications for on Interlocking Machines 331
Electric Motors:
Specifications for Switch Operating and Locking Mechanism 331
Electrical Instruments:
Esterline Company 187
Roller-Smith Co., N. Y. 227
Electric Storage Battery Co.... 227, 264, 302
Electrical Testing:
Report of Committee XIII, Signal Division 517
Electro-Mechanical Interlocking at Sunbury, Pa. 271
E.M.F. of a Loop in a Magnetic Field. 257
Electrification:
Comparison of Electric and Steam Motive Power 174
General 174
In Brazil 89
Motive Power Equipment 173
On Central of Brazil 45
On Jamean Railways 185
On North Eastern Railway 88
On Railways of Union of South Africa 26
On Steam Railroads, Discussed at Western Society, Chicago.... 185
On St. Paul 173
Reports Pertaining to on Canadian Pacific 136
Substation Equipment and Power Supply System 173
System Proposed on French Railways 53
Electric Lighting of Railway Signals.. 202
Electro-Pneumatic Interlocking at East Somerville 239
Electromagnets:
Use of 218
Electrolysis and Its Effect on Cables. 1488
Electrolysis and Its Effect on Lead Cables 527
Electrolysis:
Protection Against, Report of Committee No. 3—T. & T. Division 424
Each Bill:
Section on Automatic Train Control 29
Esterline Company, Electrical Instruments 187
- F**
- Fairbanks, Morse & Company... 90, 264, 536
Falls Rivet Company 535
Fixtures—The National X-Ray Reflector Co. 187
Fibre:
For Track Insulation 219
Insulation for Track Circuit 402
Fire Hazards 11
Fitzgerald, J. M., New Company 45
Flagging Rules, Letter to the Editor.. 231
Flath, O. S., Company, Inc., Purchased Alger Supply Company 45
Fleming's Right Hand Rule 256
Foreign Current:
In Track Circuit 69
Ft. Worth & Denver City:
Telephone Despatching Construction 534
Fuses:
Specification for Renewable Cartridge 239
Killark Electric Manufacturing Co. 438
- G**
- Galena Signal Oil Company 188
Gasoline:
Atlantic Refining Co. 438
Torch Superheater 260
Gates, Crossing:
Operated from Electro-Pneumatic Interlocking Machine 363

- Generator, Electrical:**
 Armatures *352
 Armature Reaction *352
 Characteristic Curves *480
 Efficiency of *354
 Essentials of *352
 Fundamental Principles of *380
 Magnetic Circuits in *481
 Speed of Armature *383
 Types of 478
General Electric Company 264, 536
Good Circuit Controllers:
 Adjustment, Ryan Changes His Mind *120
Grand Trunk System:
 Automatic Block Signal Construction 300
 Interlocking Construction 534
Great Northern:
 Interlocking Construction 486
Gravity Cell:
 Shunting of on Track Circuit 49
 When Is It Safe on Track Circuit? 49
Grounds:
 Method of Measuring Resistance *354
 Tests for *303
 Resistance of *139
Guantanamo Railroad of Cuba:
 Highway Crossing Protection Construction 300
 Highway Crossing Signals on *379
- H**
Handling Relays by Passenger Train. †230
Highway Crossings:
 Michigan Supreme Court Decision. 88
 Guantanamo Railroad, Cuba. 300
Highway Crossing Signals:
 American Gas Accumulator Co. 394
 Hyatt Roller Bearing Company 227
- I**
Illinois Central:
 Automatic Block Signal Construction 436
 Butting Collision at Adamsville, Ala. 210
 Construction on Markham Yards Began 185
 Indianapolis Union Station *145
Illumination—The National Lamp Works 187
Independent Pneumatic Tool Co. 227
Index:
 Signal Engineer †439
 Index for 1920, Railway Signal Engineer †487
Indianapolis Union & Pittsburgh:
 Indianapolis Union Station Telegraph Office *145
Inductive Interference:
 Causes and Effects of *468
 Report of Committee No. 7—T. & T. Division 429
 Rules for the Prevention or Mitigation of 470
 Theory of *468
Ingot Iron Wire 264
Insulated Track Joints:
 Length of Life †139
Insulated Wire and Cable:
 Handbook Published by Okonite Company 536
 Measuring the Resistance of *143
 Relation to the Track Circuit *142
 Testing of *232
Insulating Materials:
 Westinghouse Electric & Manufacturing Company 438
Insulation:
 Fibre for Track Circuits 402
 Rubber From a Colloidal Viewpoint *250
Interlocking:
 Completed in 1919 *18
 Detector Circuit Release for Electric Lock *386
 Electric Use of Lead-Covered Cables †439
 Interlocking at Bellefontaine, Ohio *110
 Electric Plant at Patio Junction. . . 59
 Electric Plant at Winchester, Kentucky *59
 Electro-Mechanical at Sunbury, Pa. *371
 Electro-Pneumatic Operates Crossing Gates *363
 Electro-Pneumatic Plant at East Somerville *239
 Facilities at Richmond, Va., on the A. C. L. *490
 Fire Hazards †1
 Largest Saxby & Farmer Machine. . . 212
 Lead Cover Paper Insulated Cable at *458
 Machine, Type P-5, Electro-Mechanical 170-333-371-506
 Outside Wiring at †439
 Power, Report of Committee III. 330-514
 Power at Bellefontaine, Ohio *110
 Proposed for 1920 *18
 Report of Committee III. 165-330
 Special Switch Fittings with Conical Bearings *298
- Specifications for Mechanical Style**
 "A" Interlocking 333
 Statistics for 1919 26
 Statistics Construction During the Past Few Years *5
 Switch Shifts Under Train 199
 Under Construction at End of 1919 *18
 Use of Underground Cables at †439
International Earth Boring Machine Corp. 535
International Western Electric Co. 394
Interstate Commerce Commission:
 Accident Bulletin No. 73 276
 Accident Bulletin No. 74 495
 Accident Investigation 278
 Block Signal Statistics †267
 Collisions Investigated in Automatic Block Signal Territory. . . 444
 Report on Butting Collision at Adamsville, Ala. 210
 Report of Butting Collision on St. Louis-San Francisco 210
 Report on Riverside, Vermont Collision *290
 Report of Collision at Trussville, Ala. 433
 Statistics on Telegraph and Telephone for Train Orders 375
 Statistics 280
- J**
John A. Roebling's Son Company. 264
Joints in Lead Cables:
 Standard Underground Cable Co. . . 438
Joints Insulated:
 Measuring Resistance of Relation to Track Circuit *142
- K**
Kinks:
 An Engine Oil Can for Quart Measure 87
 Apparatus for Locating Wires or Pipes *296
 A Tool for Extracting Cotter Pins *87
 Bell to Indicate Power Failure. *309
 Cement for Resisting Fire 260
 Crossing Bell and Pole-Changer Circuit *134
 Dry Battery and Bell Test Set. *434
 Electric Heated Solder Iron *260
 Draftsman's Triangle *387
 Dwarf Signal Blade 387
 Fishing Runs in Conduit 434
 For Motor Car 181
 How to Apply Simple Tools Effectively *297
 How to Mark Stencil on Glass 181
 Maintainer's Method of Recording Valuation Notes *180
 Match Extender *134
 Method of Filling Edison Storage Cells *388
 "Old Man" for Drilling Poles *87
 Removing Tight Pin from a Casting *296
 Repairing Adjustable Pliers 434
 Superheater for Gasoline Torch *260
 Stick Relay Circuit for A. P. B. . . *387
 Trap Circuit at Electric Crossings *180
 Wire Scraper Made from Hacksaw Blade *434
- L**
Ladder, Safety Type *467
Lake Erie & Western:
 Indianapolis Union Station, Telegraph Office *145
Lamps:
 Dry Battery Type for Motor Cars. . . *432
 For Pole Line Service 473-474
 Lighter for *134
 Testing Oil for Signal †47
 Wrong Founts and Burners in. . . 49
Lenses:
 Use and Misuse of 154
Lehigh Valley:
 Interlocking Construction 348
Letters to the Editor:
 A Cure for Unrest 306
 A.C. Signals on Industrial Tracks. . . 181
 Audible Block Signals 141
 Automatic Block Versus Train Control 268
 Automatic Signals and Strikes. . . 141
 Automatic Train Control Committee Report 94
 Classic Shades of Harvard 232
 "Custer's Last Stand" 141
 Electrical All the Way 441
 Flagging and Railroad Accidents. . . 231
 "Get It Out of the System" 233
 King Albert of Belgium Is Familiar with Signals 3
 Maintenance Rules and Instructions 397
 Minutes of Sectional Meetings 439
 Need for Automatic Train Control 96
 Safety Appliance Company Train Control 94
 Sectional Committee Meetings. . . 306
 Shunting of a Track Circuit. 49
 Signaling of Tomorrow 363
- Suggested Improvements in D.C. Track Circuit** †355
 Super-Refined Block Signaling. . . 191
 Testing Insulated Joints †232
 Train Staff System and Accidents. . . 306
 What's the Answer? 441
 When Is a Track Circuit Safe? . . 355
 Wrong Founts and Burners in Lamps 49
Light:
 Portable Electric Flood *183
Lighting Data:
 Edison Lamp Works 438
Lightning:
 Protection Against, Report of Committee No. 4—T. & T. Division. . . 425
 Resistance of Grounds 139
Lighting Engineering:
 General Electric Co. 438
 Lineman's Body and Safety Belt. . . *183
 Line Wire Joints Welded Prove Efficient 97
Line Wire:
 Welding Iron Joints 478
 Welding Process for Joints *99
Locks, Electric:
 Circuit for Route Locking *386
London & Northwestern:
 Switch at Interlocking Shifts Under Train 199
Long Island:
 How Maintenance Organization Conducts Work *17, 122
 Signal Failures Reduced to a Minimum *16, *122
Louisville & Nashville:
 Electric Interlocking at Patio Junction *59
 Electric Interlocking at Winchester, Ky. *59
 Experiments with Wireless 254
 Highway Crossing Construction. . . 436
 Installs Radio Telegraph Apparatus at Louisville 185
 Ordered to Re-establish Telegraph Service in Alabama 300
 Radio Telegraph and Telephone on Train Operation by Means of Signal Indications *208
 Low Voltage Switch Machines, Use of. . . *50
- M**
Machine:
 For Boring Holes and Setting Poles *388
Magnetic Circuit *217
 Study of for Beginners *177
Magnetic Field:
 About a Straight Wire *215
 Produced About a Loop of Wire. . . *216
 Produced by a Solenoid *217
 Study of for Beginners *177
Magnetic Induction *177
Magnetism, Study of for Beginners. . . *176
Magnetic Flux *217
Magnetic Flux in Magnetic Circuits. . . *217
Magnetic Saturation of Magnetic Materials *218
Magnetomotive Force *217
Maintenance:
 Automatic Train Control 449
 Discussion of Rules and Instructions 65
 Effect of Government Control on Work Performed 19
 Letters to the Editor on 397
 Program for Winter Work †47
 Neat Signal Locations †229
 Rules and Instructions, Report of Committee V. 313
 Rules and Instructions †303, 397
 Malleable Iron, Booklet on 90
Manual Block Signals:
 Completed in 1919 *18
 Installed in the United States Since 1909 *18
 Statistics for the Past 15 Years. . . *5
Manufacturers' Sales Company:
 Changes Name to Bradford Sales Co. 535
Mechanical Interlocking:
 Report of Committee II. 170
 Specifications for Style "A" Machine 333
Mechanical Memory System:
 Booklet Explaining 46
Melbourne Electrified Railways, Signaling on *194
Message Traffic:
 Report of Committee No. 6—T. & T. Division 426
Meters:
 For A.C. Signal Testing 435
 For Locating Trouble on Battery. . . *390
 Indicating Type for Measuring Ohms *389
Methods of Inducing E.M.F. *253
Micrometers:
 Read Small Tool Works 45
Missouri Pacific:
 Interlocking Construction 393
Missouri, Kansas & Texas:
 Light Signal for Crossing Protection 88
 Automatic Block Signal Construction 262

- Money Order for Railway Signal Engineer Lost in the Mail †229
 Motor and Hand Car Rules 233
 Motor Car:
 For One-Man Operation *183
 Improved Ignition for *182
 Preventing Oil from Being Thrown Out Between Drive Belt Wheel 181
- N**
- Nashville, Chattanooga & St. Louis:
 Collision at Rockledge, Tenn., Suit Decided †190, 220
 Radio Telegraph & Telephone on 385
 National Agreement for Signalmen Signed 55
 National Lamp Works:
 Pamphlet on Illumination 187
 National Railway Appliance Exhibit †91, *105
 National X-Ray Reflector Co.:
 Pamphlet on Fixtures 187
 New Books:
 Explanation of Train Rules and Train Orders 397
 Inventions, Their Purchase and Sale 268
 Non-Technical Chats on Iron and Steel 268
 Tin, Sheet Iron and Copper Plate Worker 397
 Westinghouse E-T Air Brake Instruction Pocket Book 231
 New Devices:
 A New Car for One-Man Operation *183
 Collapsible Canvas Tool Bag for Linemen *135
 Combination Signal Foundation and Battery Cellar *135
 Continuous Rail Crossing *391
 Current Transformer *533
 Electrical Formulas, Drawings and Problems 231
 Electrical Instrument for Locating Trouble *390
 Extension for Wood Poles *183
 Eymon's Continuous Rail Crossing Highway Crossing Flagman *184
 Highway Crossing Signal *261-533
 Hole Boring and Pole Setting Machine *388-483
 Improved Ignition for Motor Cars *182
 Improved Mercury Time Release *181
 Improved Rail Joint Expander *183
 Kleinschmidt Printing Telegraph *390
 Lineman's Body and Safety Belt *182
 Meters for A.C. Signal Testing 435
 New Instantaneous Cell Tester *182
 New Type of Printing Telegraph *435
 New Welded Bonds for Track Circuit *297
 Ohmmeter, Indicating Type *389
 Portable Drilling Machine *533
 Portable Electric Flood Light *183
 Railway Grade Crossing Signal *184
 Ratchet Adjustable Cutter *435
 Rectifier for Charging Storage Cells *389
 Reinforced Thawing Torch *261
 Switch Fittings with Conical Bearings *298
 Tool for Removing Storage Battery Covers *483
 New York Central:
 Automatic Train Control Experimental Installation Requested on 392
 Interlocking Construction 88-186
 Rear Collision West of Schenectady, N. Y. 300
 Wireless Telephone Experiments on 185
 New York Municipal Railways:
 Automatic Block Signal Construction 348
 New York Railroad Club:
 Automatic Train Control Problems Discussed 206
 On Train Control 148
 New South Wales Government Railways:
 Organization of Signal Department *63
 New Year's Greetings †1
 Norfolk & Western:
 Collision at Walton, Va. 144
- O**
- Oahu Railway & Land Company:
 Automatic Block and Signal Construction 300
 Ohmmeter:
 Indicating Type *389
 Oils:
 Report of Committee XVI on 312
 Specifications for 163
 Testing of for Signal Lights †47
 Oil Burning Appliances 90
 Okonite Company 535
 Organization:
 Conditions Which Tend to Lower the Morale of †304, 305
 Oxweld Acetylene Co. 227, 394
- P**
- Page Wire & Steel Company 228, 264
 Passenger Trains:
 Handling Relays On †230
 Pennsylvania, Lines West:
 Interlocking Construction 88
 Pennsylvania System, Central Region:
 Interlocking Construction 186
 Pennsylvania System, Southwestern Region:
 Interlocking Construction 186
 Pennsylvania System:
 Interlocking Construction 534
 Pennsylvania Railroad:
 Landslide at Pittsburgh, Pa. 489
 Personnel:
 Changes in the Signal Supply Field Philadelphia & Reading:
 Automatic Block Signal Construction 88
 Electric Interlocking Construction 222
 Electro-Mechanical Interlocking at Sunbury, Pa. *371
 Interlocking Construction 89
 Pictorial:
 Blizzard Hits Eastern States *109
 Crossing the Canadian Rockies *249
 Iron Ore from the Mine to the Furnace *67
 Swiss Railway Engineers Overcome Great Obstacles *279
 Pipe Cutting & Threading Tools 89
 Pipe Threading Equipment—The Borden Company 187
 Pipes:
 Apparatus for Locating *296
 Ingot Iron for Pipes 65
 Manufacture of 64
 Methods of Refining Crude Iron for 65
 Methods of Welding 65
 Poem:
 To a Signal Engineer 252
 Poles:
 Iron:
 Old Man for Drilling *87
 Pole Line:
 Construction †355
 Construction and Maintenance of *417
 Damaged by Airplane 433
 Factor of Safety for *364
 For Telegraph and Signal Service *364
 Hole Boring and Pole Setting Machine *483
 Machine for Boring Holes and Setting Poles *388
 Methods of Calculating for Safety *364
 Report of Committee XVII 334
 Position Light Signals *234
 Portable Welding Outfits 90
 Portable Steel Buildings:
 Blaw-Knox Co. Issues Pamphlet on 438
 Pothead:
 Specifications for Making for Paper Insulated Cable 461
 Power Interlocking:
 At Winchester, Kentucky *59
 Electro-Pneumatic Plant at East Somerville *239
 Facilities at Richmond, Va., on A. C. L. *490
 Federal Signal Co., Indication Magnet. Explanation of Circuits *60
 Report of Committee III 165, 330, 514
 Power Operated Track Drill *295
 Practical Lessons in Electricity for Beginners *522
 Primary Battery Division:
 Thomas A. Edison, Inc., Purchases Patents 350
 Problems for Solution †487
 Letter to the Editor 441
 What's the Answer 477
- R**
- Rail:
 Resistance of in Track Circuit *68
 Rail Joint Expander:
 Chicago, Railway Signal & Supply Co. 90
 Rail Joint:
 Improved Extender for *183
 Railroads:
 Fight Snow and Ice *108
 New Legislation for †92
 Problems for Solution 379, 441
 Radio Telegraph and Telephone on 385
 Rules of Long Ago 3
 Viewpoint on Automatic Train Control 449
 Railroad Labor Board:
 Announces Its Decision for Signal Employees 345
 Classifies Subordinate Officers 433, 489
 Wage Hearings Before 299, 243, 433
 Railroadings:
 French Opinion of, in America 133
 Railways of Japan:
 Order Block Signals 222
 Railway Signal Engineer:
 Index for 1920 †487
 Policy of 465
 Railway Signaling Text Book Corporation 90
- S**
- Railway Signalmen's Bowling League, St. Louis 136
 Reclamation of Signal Material †488, 499
 Rectifiers:
 Charging Storage Batteries for Signals by 276
 Chemical Type Tests for Telegraph Service *292
 Electrical Characteristics of Mechanical Type *400
 Electrolytic Type *401
 For Charging Storage Batteries *398
 For Storage Battery Charging Signal Service †266
 Limitations and Range of Mechanical Type for Signal Service *401
 Mechanical for Charging Signal Storage Cell *389
 Mechanical Type for Storage Cell. Principles of Mechanical Type *400
 Regan Safety Devices, Automatic Train Control *204
 Regan Train Control in England *463
 Relays:
 Direct Current 161
 Direct Current, Report of Committee VII 329
 Handling by Passenger Trains †230
 Specifications for Tractive Armature Direct Current 329
 Reluctance of a Magnetic Circuit *218
 Rickard & Sloan, Inc. 350
 Rockledge, Tenn.:
 Collision on the Nashville, Chattanooga & St. Louis †190
 Collision on Nashville, Chattanooga & St. Louis Suit Decided 220
 Roller-Smith Company, The 45, 350, 438
 Roundels:
 Use and Misuse of 154
 Rubber Insulation:
 A Study of Colloidal Viewpoints *250
 Rubber Insulated Wire:
 Standard Underground Cable Co. 228
 Rules:
 Flagging and Railroad Accidents 231
 Motor and Hand Car Rules 233
 On Maintenance of Signals †303
 Rutland Railroad:
 Collision at Riverside, Vermont, Report on *290
- S**
- Safety Appliance Co., Train Control... 94
 Safety First:
 Some Pointers on 497
 Safety Measures:
 "Don't Take Chances" 3
 Sectional Committee Activities 495
 Chicago Sectional Committee 338
 Cincinnati Sectional Committee 338
 Letter to the Editor on 306
 Sectional Committee Meeting:
 Chicago Section 373, 410, 476
 Cincinnati Section. 203, 374, 476, 499, 495
 Comments on Attendance at 306
 How Often Should They Be Held. 1440
 Kansas City Sectional Meeting 262, 338, 373, 476, 489
 Letters to the Editor on 306
 Minutes of, Letters to the Editor. 489
 New York Sectional Committee 222, †230, *234, 410, 476, 495
 Rochester Section 495
 Savannah, Georgia, Section 476
 Sectional Committee 148
 Sectional Committee Meeting 1396
 St. Louis Sectional Committee 203, 338, 356, 398, 410, 476, 495
 St. Paul Section Considers Soda Cell 253, 373, *406
 Texas Sectional Committee 222, 373
 Shadle Automatic Train Control Tests. *404
 Signal:
 Failure Caused by Rough Handling of Relay on Passenger Train †230
 Failure to Observe 457
 For Better Operation *270
 For Crossings on Cuban Railroad. *379
 Foundation and Battery Cellar Combined *135
 Grades and Curves Effect Location of *7
 Highway Crossings *261
 Highway Crossings, New Devices. *533
 How to Test †487
 Light Signals on Victorian Railways, Melbourne, Australia... *196
 Light to Supplant Semaphore... *234
 Location from Braking Distances. Locating from Braking Distances, a Correction 107
 Maintenance Program for Winter Work †47
 Neat Locations †229
 On Industrial Tracks 191
 Pole Line *364
 Position Lights 88
 Railway Grade Crossings *261
 Reclamation of Material for †488
 Special Circuit Saves Money *53
 Stick Relay Circuit for A. P. E. *387
 Temporary Blade for Dwarf 387
 Signal Accessories Company 138

Signal Accessories Corporation.....	350	Department Organization of on New South Wales Government Railways.....	*63	Storage Batteries.....	486
Signal Construction:		D. C. Operated from A. C. Source.....	†266	Charging and Cut-off Charge.....	118
Boston Elevated.....	222	D. C. Operated by Alternating Current.....	276	Hospital Cases.....	119
Central Railroad of New Jersey.....	223	Electric Lighting of.....	202	Lead Type, Care of.....	192
Philadelphia & Reading.....	222	Equipment on the Long Island.....	*17	Lead Type; General Principles of.....	117
Railways of Japan.....	222	Failures Reduced to a Minimum.....	†2, *16, 122	Putting Cells into Service.....	*81
Signaling:		Reclamation of Material for.....	499	Standard Design:	
Absolute Permissive Block.....	*356	Relieve Traffic Congestion.....	†140	Report of Committee VI.....	*322
A. C. Automatic Block, Report of Committee VIII.....	517	Saving to Be Secured by Use of.....	*50	Story:	
A. P. B. Stick Relay Circuit.....	*387	Specifications for Universal.....	166	Haw Hand on the Zillah.....	*36
As Sketched by a Signalman.....	*299	Time Interval Method.....	*270	St. Louis-San Francisco:	
Automatic Block vs. Train Control.....	268	Use of at Outlying Switches.....	*50	Butting Collision at Adamsville, Ala.....	210
Block Signaling on the Melbourne Electrified Railways.....	*194	Use of Low Voltage.....	*50	Subordinate Officials:	
Building for the Future.....	†230	Signal Section, A. R. A.:		New Definitions of.....	489
Completed in 1919.....	*18	As a Separate Section.....	†354	Subscriber:	
Conditions During 1919.....	26	Committee II—Mechanical Interlocking.....	170, 333	Ordering Indexes for Signal Engineer.....	†439
Construction Costs During 1919.....	*14	Committee III—Power Interlocking.....	165, 330, 514	Renewals to Railway Signal Engineer.....	†189-†229
Construction During 1919.....	*18	Committee IV—D. C. Automatic Block Signaling.....	503, 509	Subscription:	
Construction Requirements to Bring up to Normal.....	*4	Committee V—Maintenance Rules and Instructions.....	313, 503	Rates Increased.....	†395
D. C. Automatic Block, Report of Committee IV.....	509	Committee VI—Standard Design.....	*322, *519	Sudden Ravings *337, *385, *430, *475, Superheater for Gasoline Torch.....	*526
D. C. Operated From A. C. Source.....	†266	Committee VII—Direct Current Relay.....	161, 329, 503	Switch Machine:	
D. C. Operated by Alternating Current.....	276	Committee VIII—A. C. Automatic Block Signaling.....	503, 517	Advantages Use of Low Voltage..	*53
Effect of Government Control.....	19	Committee IX—Wires and Cables.....	168, 326, 503	Control of Outlying Switches by Low Voltage.....	*51
Facilities at Interlocking on A. C. L. at Richmond, Va.....	*490	Committee X—Signal Practice 321, 506		Increased Safety by Use of Low Voltage.....	*50
For Better Train Operation.....	*270	Committee XI—Batteries.....	*323, 505	Low Voltage Switch and Lock Movement.....	*52
How One Road Conducts Work.....	122	Committee XII—Electrical Testing.....	*334, 503, 517	Saving to be Secured by Use of.....	*50
How One Road Reduced Failure to a Minimum.....	*16	Committee XIII—Valuation.....	333	Specifications for Universal.....	166
King Albert of Belgium Is Familiar With.....	3	Committee XVI—Oils.....	163, 312, 503	Use of Low Voltage.....	*50
Light.....	*234	Committee XVII—Pole Lines.....	334, 503	Use of at Outlying Switches.....	*50
Maintenance Program During Winter.....	†47	Committee XVIII—December Stated Meeting.....	†488-503	Table:	
Maintenance Rules and Instructions for Report of Committee V.....	313	Electrical Testing.....	†487	Use in Signal Service.....	154
Manual vs. Automatic Block.....	269	Holds Fifth Meeting.....	*156	Telegraph:	
Methods to Indicate Stop in Emergencies, Report of Committee X.....	321	How Far Should It Consider Standardization.....	†488	Alternating Sounder.....	474
Oils for, Report of Committee XVI.....	312	How Often Should They Be Held. Letter to the Editor on "An Average Member".....	233	Automatic.....	474
Practical Lessons for Beginners.....	*126	Limits of Standardization.....	†140	Kleinschmidt Printing Type.....	*390
Practical Lessons for Beginners.....	*38-79	March Meeting.....	†91-107-533	Office at Indianapolis, Modern.....	*145
Practical Lessons for Signalmen.....	†1	Review of Activities.....	504	Phantom Wiring.....	475
Practice, Report of Committee X.....	321	Sectional Committee Activities.....	495	Pole Line.....	*364
Position Light.....	*234	Sectional Committee Meetings.....	†396	Potts Simplex Printer.....	474
Power Interlocking, Winchester Ky.....	*59	Sectional Committee Meeting Discusses Low Voltage Switch Machines.....	*50	Printing Type, New.....	*435
Proposed Expenditure for.....	392	Sectional Meetings: Minutes of, Letters to the Editor.....	489	Relieving Congestion on Line.....	442
Proposed for 1920.....	*18	Second Annual Convention.....	*310	Use for Train Orders.....	*375
Progress Made During 1919.....	†2	Second Annual Convention Activities.....	335	Wire Message Capacity Increased.....	198
Reclamation of Material for.....	†488	Sidelights on.....	141	Telegraph and Telephone:	
Signaling Practice:		Signal Section, A. R. A., Annual Meeting.....	†229-238-†265	Alternating Current Sounder.....	474
Report of Committee X, Signal Division A. R. A.....	506	Signaling Practice.....	503	Construction Costs During 1919.....	*14
Ryan Changes His Mind.....	120	Signal Terms; Importance of Knowing.....	†47	Development of, Report of Committee No. 5, T. & T. Division.....	425
Single Track on Southern Pacific.....	360	Signs:		Motor Generator Bench.....	474
Situation During the Past Year.....	*18	For Highway Crossing Protection.....	*431	Radio Type in Railroad Service.....	385
Space Interval Method.....	*271	Situation in Signal Field During 1919.....	†2	Recent Developments of.....	473
Special Circuit Saves Money.....	*53	Snow Melter:		Telegraph and Telephone:	
Standard Design for, Report of Committee VI.....	*322	Electric Operated for Switches.....	*245	Sending Machine.....	473
Standardization of Apparatus.....	†266	Reinforced Thawing Torch.....	*261	Story of an Operator on the B. R. & N.....	*36
Standardization of Apparatus by Signal Division.....	†354	Soda Cell:		Used for Train Orders.....	*375
Straight Automatic on the Union Pacific.....	359	Setting Up of.....	253	Visual Signal Box.....	474
Summary of Automatic Signal Failures on Long Island.....	125	Shunting of on Track Circuit.....	49	Telegraph and Telephone Division A. R. A.:	
Super-Refined Block.....	191	Study of in Plain Language.....	253	Annual Meeting...†353, 374, *414,†396	
Time Interval Methods.....	*270	Study of.....	154	Appointments.....	487, 534
Time Interval vs. Space Interval Compared.....	273	When Is It Safe on Track Circuit?.....	49	Committee No. 1—Construction and Maintenance Outside Plant.....	417
Train Operation by Indication.....	268	Soldering Iron Heated by Electric Arc.....	*260	Committee No. 2—Construction and Maintenance Inside Plant.....	423
Train Operation by Means of Under Construction at End of 1919.....	*18	Southern Pacific:		Committee No. 3—Protection Against Electrolysis.....	*527
Union Switch & Signal Co., Bulletin on Remote Switch Control.....	350	Collision on Portland Division Near Bertha, Ore.....	262	Committee No. 4—Protection Against Lightning, Electric Light and Power Circuits.....	425
What Scheme Is Most Desirable? With Automatic Train Control.....	*356	Crossing Gate Operated by Electro-Pneumatic Interlocking.....	*363	Committee No. 5—Telegraph and Telephone Development.....	†425, 473
Signal Lamps:		Southern, Western Lines: Interlocking Construction.....	88-89	Committee No. 6—Message Traffic.....	426
Testing Oil for.....	†47	Statistics:		Committee No. 7—Inductive Interference.....	†429, *468
Wrong Founts and Burners in.....	49	Automatic Block Signals.....	19	Committee of Direction Report.....	414
Signal Material:		Automatic Block Signals for the Past 15 Years.....	*4	Electrolysis and Its Effects.....	†488
Depreciation of.....	†139	Block Signal.....	†267, *280	Pole Line Construction.....	†355
Signalmen:		Block Signaling.....	19	Special Committee on Future Activities Report.....	416
Classification of.....	55	Block Signaling During 1919.....	*18	Sub-Committee "A"—Construction and Maintenance of Pole Lines.....	*417
Discipline and Grievances.....	57	Fatalities to Non-Trespassers on Railroad.....	31	Sub-Committee "B"—Wire Crossing.....	421
Hours of Service, Overtime and Calls.....	56	For the Past Five Years.....	*4	Sub-Committee "C"—Underground Construction.....	*422
Miscellaneous Clauses in National Agreement.....	58	Manual Block Signaling for the Past Fifteen Years.....	*5	Sub-Committee "D"—Transpositions.....	423
National Agreement for Signed.....	55	On Block Signals, Comment on.....	†304	Telephone:	
Promotion of.....	57	Use of Telegraph and Telephone for Train Orders.....	*375	Operators' New Receiver.....	474
Rates of Pay for.....	57	Standardization:		Repeaters.....	475
Seniority.....	56	Of Signal Apparatus.....	†266	Train Orders by.....	477
Signals:		Standardized Concrete, Koehring Machine Co.....	264	Use of in Train Despatching.....	*11
Audible.....	141	Standard Underground Cable Co.....	89, 138	Use for Train Orders.....	*375
Automatic Block Construction on the M. K. & T.....	262	Steel Castings:		Wireless Experiments on New York Central.....	185
Construction Costs During 1919.....	*14	"Harrison Steel Castings".....	90	Telephone and Telegraph:	
Construction January 1, 1915, to January 1, 1920.....	*4	Steel Sales Corporation, Chicago.....	187	Statistics for Train Orders.....	375
Construction Requirements for the Next Three Years.....	*4	Stencil on Glass, How to Mark.....	181	Testing:	
Construction Camp Car.....	†265	Storage Cell:		Electrical for Signals, Report of Committee XIII.....	517
Definition of Terms, Important to Know.....	†47	Chemistry of.....	117	Signals Electrically.....	†487
		Discharge of.....	118	Test Set:	
		Electrolyte of.....	119	Composed of Dry Battery and Bell.....	*434
				Thompson Electric Company.....	138

The J. W. Murphy Company.....	536	Train Control Automatic: (See Automatic Train Control)		Victorian Railways, Block Signaling on at Melbourne, Australia.....	*194
Ties:		Train Control Devices:		Vocational Training for Signalmen	†265, 286
Burning of Under Signal Wires...	†190	Classification of.....	83		
Tight Pins Removed from Castings...	*296	Continuous Electrical Contact Type.....	86		
Time Release:		Electrically Controlled Mechanical Trip.....	84		
Improved Mercury.....	*181	Induction Type.....	85		
Applied to Signal or Switch Ap- paratus, Report of Committee X.....	321	Induction Type, Non - Magnetic Rail.....	85		
Timber Preservation, Bulletin on.....	438	Induction Type with Inert Road- side Element.....	85		
Toledo & Ohio Central: Installation of Color Light Signal on.....	137	Insulated Truck, with Short Track Circuit.....	85		
Tool Bag:		Intermittent Electrical Contact.....	84		
Collapsible for Linemen.....	*135	Intermittent, Non-Contact Plan.....	84		
Tools:		Plain Mechanical Trip.....	84		
Bonding Drill.....	138	Wireless Type.....	86		
For Extracting Cotter Pins.....	*87	Train Despatching.....	271		
How to Apply Simple Ones Effec- tively.....	*297	"Booster" Telephone Set Used for Experience Developed Improve- ment in Use of Telephone.....	*11		
Old Man for Drilling Pole.....	*87	French Opinions of American Practice.....	133		
Pipe Cutting and Threading.....	89	"High Efficiency" Telephone Set Used for.....	*11		
Track Circuits:		Principles of.....	275		
A Handy Calculator for.....	179	Results Developed by Telephone.....	*11		
Basic Curves for.....	*70	Train Orders by Telephone.....	477		
Ballast and Rail Resistance in.....	*68	Train Order Signals.....	271		
Ballast Resistance in.....	*68	Train Orders vs. Signal Indications...	339		
Bonded Joints Gas Welded.....	*284	Train Operation:			
Cincinnati Sectional Committee Meeting Considers.....	499	By Time Tables.....	*272, *270		
Comparing Shunting Effects with Gravity and Soda Cells.....	*10	By Train Despatching.....	*271, *272		
Curves Showing Results of Tests...	*10	By Train Orders.....	*272		
Cut Sections.....	*69	By Train Order Signal.....	*271, *272		
D. C. Suggested Improvements in...	355	By Signal Indication.....	268		
Discussion on.....	*75, *77, 78	By Space Interval Method.....	271		
Fibre for Track Insulation.....	219	Signals for.....	*339		
Fibre Insulation for.....	402	Signal Indications Provide Means of.....	*208		
Foreign Current in.....	*69	The Use of Signals for.....	*270		
Improving of.....	†267	Train Operation by Signal Indication, Bulletin Issued.....	228		
Letter to the Editor.....	355	Train Sign:			
Maximum Rail Resistance in.....	*73	Used as Indicator.....	*86		
Measurement for Center Fed Type...	*408	Operated by Signal Motor for Indicator.....	*86		
Measurement of End Fed Type.....	*408	Transformer:			
Method of Calculation.....	*70	Current Type, New Device.....	*533		
Minimum Ballast Resistance in.....	*73	Transportation Engineering Cor- poration.....	227, 264		
Multiple vs. Series-Multiple Bat- tery Connections.....	*74	Transpositions:			
New Welded Bonds for.....	*297	Report of Sub-Committee "D" T. & T. Division.....	423		
Proposed New.....	*287	Two Dollars Saved by Spending Two Cents.....	†229		
Rail Resistance in.....	*68				
Relation to Insulated Joints.....	*142				
Report by St. Louis Sectional Committee.....	203				
Rusty Rails on.....	141				
Safety Factor for.....	*68				
Shunting of.....	49				
Standards of Track Circuit Main- tenance.....	*75				
Studies of.....	*406				
Study of Conditions Affecting.....	*68				
Suggested Improvements in D. C. ...	*287				
Testing Insulated Joints.....	*232				
Track Circuit:					
Tests to Show Conditions.....	*10				
When is it Safe.....	96, 49, 192, 355				
Track Drill:					
Power Operated.....	*295				
Track Insulation:					
Discussion on.....	119				
Discussion of at Sectional Com- mittee, Meeting at St. Louis...	*115				
Fibre for.....	192				
Paper on at St. Louis Sectional Committee.....	*115				
Specification for.....	*116				

PERSONAL MENTION

(Photographs are indicated thus.* Obituaries are indicated thus†)

A		Buehler, M. A.....	188	Cullinan, J. S.....	188
Ackerman, Charles V.....	486	Bullard, William Ellery.....	†186	Curtis, F. S.....	223
Alford, V. C.....	301	Bullock, E. H.....	263	Curtis, W. H.....	436
Alig, P. A.....	225	Burwell, P. V.....	535	Cutshall, Harvey W.....	*351
Allison, W. E.....	438	Brown, G. E.....	188		
Ambrach, E. T.....	89			D	
Anderson, William.....	437			Dahlstrom, H. R.....	263
Annear, R. F.....	187			Dalley, George W.....	393
Appleton, Harry H.....	45, *137, 349			Danielson, Otto.....	138
Austin, J. W.....	264			Darlington, R. L.....	46
				Day, T. R.....	226
B				Day, Tom R.....	*302
Bagnall, R. V.....	437			Day, L. R.....	438
Baker, B. H.....	485			Deardorff, Clyde M.....	*351
Baker, H. D.....	350			Deaville, C.....	225
Bauer, W. F.....	187			Dennis, John B.....	188
Baxter, Sidney L.....	263, 300			Dennison, E. B.....	138-438
Beasley, Benjamin F.....	187, 224			Doles, J. B.....	437
Beaumont, Joseph.....	350			Dower, D. W.....	263, 534
Behner, Le Roy.....	187, *226			Drake, Lauren J.....	188
Bender, Fred W.....	*187			Duffy, C. M.....	187
Berggren, O. E.....	89			Duncan, Otis B.....	536
Bernstein, Benjamin.....	90				
Black, E. A.....	89			E	
Blizard, Charles.....	†302			Elfborg, H. G.....	90
Borngeesser, R. H.....	225			Elliot, E. B.....	138
Bradley, C. W.....	224			Ellis, G. E.....	228
Brandenburg, L.....	535			Entelman, Edward.....	485, *535
Brofos, E. A.....	394			Everett, Edward A.....	302
Brooks, R. E.....	436			Eves, R. D.....	138, 187
Buchanan, F. H.....	187				

F

Fearey, Frederick T.	89
Finch, J. C.	137
Fisher, R. B.	90
Fitzgerald, J. M.	45
Flagan, George	437
Ford, Stewart H.	227
Fowler, C.	437
Foster, C. S.	45
Foster, E. J.	392
Frankel, Mortimer	350, 394
Frankenberger, A. L.	138
Frantz, J. A.	485
Fries, S. W.	438
Frost, S.	45
Fullam, R. J.	186
Fuller, D. W.	392
Furman, Benjamin	348, 392

G

Gardner, R. C.	437
Gollos, Anatol	534
Gommel, J. S.	264
Gensheimer, J. S.	45, 349
Geer, Maurice, F.	352
Golings, C. E.	225
Goldman, Harry S.	90
Goodwin, P. E.	485
Gort, Godfrey	536
Grauber, George Albert	1536
Green, Dan H.	46
Gray, A. E.	437
Green, R. E.	138
Greenfield, Sidney	138
Grindell, James C.	394, 486
Grubbs, T. S.	228
Guess, W. G.	392
Guthrie, L. A.	437, 534

H

Haines, H. A.	225
Hall, E. J.	392
Hall, Thomas L.	438
Hancock, H. P.	393
Haney, F. E.	187
Hanley, John H.	90
Hansen, P. B.	438
Hansler, George B.	349
Hare, K. R.	264
Harland, W. H.	535
Harrold, A. E.	486
Hartman, C. N.	348
Hartvig, C. E.	187, 224
Hattery, C.	187
Hewitt, C. L.	436
Hillis, A. W.	138
Hinds, Charles A.	348-393
Hinds, Robert Theodore	393, 348
Hixon, Clement W.	226
Hochette, C. W.	188
Hoffman, G. N.	138
Hoffman, W. A.	348, 394
Hooper, F. H.	436
Horton, W. D.	46
Hixson, C. W.	187
Hulatt, H.	436
Humphrey, A. L.	228
Hunt, C. M.	350
Hunt, Jr., W. P.	90
Hunter, A. W.	534

I

Ireland, E. E.	301
Ishler, O. A.	535

J

Jaeger, Fred	138
Jacques, J. A.	138
Jackson, W. A.	485
James, Jr., Henry C.	349, 301
James, Julian	394
Johnson, Sidney G.	351
Jones, Julian D.	187, 226
Jones, P. W.	89
Johnson, Robert C.	89
Jordan, L. F.	188

K

Kay, Harry J.	301, 348
Kahant, C. G.	350
Kearnton, T. H.	485
Kelley, J. H.	138
Kelley, I. T.	46
Keenan, E. C.	186
Keener, Ire Earl	437, 485
Kiehm, L. L.	89
Kiehm, S. S.	263
King, E. L.	89, 485, 535
Kircher, J. G.	264
Kirsch, J. I.	350
Kirkpatrick, C. W.	223
Knight, Harold	137
Kochensperger, C. M.	436
Komorowski, Joseph Emil	392, 437

L

Laufenberg, W. H.	138
Lancaster, William	138

Larkin, John J.	89
Lavarack, P. C.	352
Lefold, G. H.	45, 350
Lepper, Oscar	138, 227, 264
Linnahen, J. E.	188
Lindstrand, J. A.	227
Looney, T. C.	534
Longace, J. J.	89
Loomer, J. G.	138
Lyon, C. A.	45
Lundy, B. A.	137
Luther, Geo. D.	350

M

McCall, A. J.	138
McCartney, J. M.	225
McCallum, H. B.	187
McCormick, Charles H.	485
McCreary, Oliver Linton	263
MacCrellish, W. H.	227
McCullar, L. C.	437
McDermott, Austin	437
McFarland, E. R.	89
McFarland, J. P.	186
McGann, W. H.	138
McKeen, A. H.	263
McNeely, J. G.	227, 264
Malone, George B.	394
Mansfield, Clarence	392
Marker, Clarence M.	226-301
Mann, L. R.	138, 188
Martin, C. A.	138
Mathley, Michael B.	350, 394
Meek, R. W.	137
Modlin, E.	436
Miller, J. A.	225
Miller, J. French	188
Miskelly, S.	187-438
Merrill, D. A.	186
Morgan, E. R.	138
Murphy, Jr., Franklin	90
Murphy, Sr., Franklin	90
Mutchler, C. B.	436

N

Nevins, J. V.	436
Nicholas, C. A.	263
Nicholson, John J.	90
Noble, William S.	394
Norris, T. A.	392

O

O'Meara, T. J.	137, 186
----------------	----------

P

Palmetier, J. A.	223
Parker, L. A.	225
Partridge, G. F.	392
Passino, Fred J.	227
Patenall, F. P.	89
Pateron, R. A.	227
Patterson, A. J.	262
Patterson, W. H.	227
Pence, Elden Monroe	225
Pendorf, P. G.	138
Phillips, W. R.	138
Pierce, C. H.	263
Pietz, Theodore A.	349-393
Porter, George Hull	138-394
Post, Ernest K.	225
Post, W. M.	187, 226
Pressinger, Whitfield P.	302
Price, H. C.	263
Printz, E. A.	138
Proestler, Louis	437
Pry, Edward B.	187, 225
Pyle, George Lester	348, 437
Pudney, Earl H.	223
Putnam, L. J.	263

R

Raber, J.	263
Raber, Samuel Gale	349
Rainey, P. A.	349
Ray, J. L.	227
Rees, M. D.	188
Regan, James B.	350
Rex, C. D.	348
Rhea, Frank	393
Richards, Elmer	349
Ripley, Edward P.	137
Roberts, C. E.	138
Robinson, B. S.	45-350
Roett, J. D.	350
Rhoads, Stanley	186
Roh, Charles J.	90
Roll, Dan K.	262, 301
Romney, Leo	394
Ross, Victor N.	263, 301
Ross, William B.	264
Rudd, Alexander Holly	187, 223
Ryan, F. E.	350
Ryan, F. R.	264
Ryan, Jack F.	138

S

Sager, Alvin	392-437-485
--------------	-------------

Sandrus, C. L.	393
Sargent, Snowdown C.	352
Seaman, J. C.	89
Seltz, Warren W.	393-437
Schmidlapp, Carl J.	485
Schneider, Franklin	90
Schott, W. J.	138
Schwenck, A.	138
Schwendt, B. J.	224
Scott, J. E.	223
Sedgwick, E. V.	188
Shaver, A. G.	223
Schaffer, C. M.	223
Sheets, Robert A.	393-437
Shire, W. J.	340
Shorono, I. A.	138
Siemens, J. F.	437
Simclair, Robert	328
Skellie, W. A.	437
Skinner, H. S.	188
Simp, J. E.	524
Small, F. F.	524
Smith, John	188
Smith, E. F.	392
Smith, F. E.	534
Smith, F. W.	437
Smith, J. W.	138
Smayle, W. R.	534
Snow, Fred W.	224
Spangler, W. N.	187, 225
Stager, D. H.	225
Stanton, Henry L.	392-485
Stelger, G. R.	437
Stephens, Earl W.	437
Stephens, M. L.	45
Spahn, H. W.	138
Spain, Kenneth Wesley	187-263
Stanton, H. B.	138
Stephens, Charles	224
Stevens, George W.	1535
Stevenson, S. J.	392
Stone, D. M.	138
Storms, Jack H.	263, 301
Stradling, E. G.	262
Strauss, Frederick	188
Stuard, James	138
Stull, L. E.	188
Sullivan, Roger C.	227
Summers, F. B.	186
Sutton, J. F.	350
Swonger, W. A.	350

T

Tasker, A. H.	349
Taylor, F. J.	535
Theiss, James R.	437
Thorn, C. C.	225
Toft, Guy	349
Tenbroeck, R. W.	138
Tolliver, A. C.	186
Tompkins, W. H.	138
Thomson, A. B.	138
Trombly, W. A.	186
Trubee, W. A.	188
Turner, Robert S.	45

V

Veale, Clinton A.	224, 263, 301
Vestal, G. C.	437
Viehoff, C. C.	90

W

Wallace, C. M.	45, 350
Walsh, W. J.	188
Walters, Lewis Clayton	300, 348
Ward, Jr., B.	350
Warner, Jr., Edward A.	438
Way, A. B.	394
Werthmuller, L. S.	485
Wharton, Charles R.	138
Wheatley, Tom	138
Whitcomb, Charles A.	187, 224
Whitcomb, L. L.	89
White, E. C.	263
White, F. W.	223-302
Whitehurst, Roland	350, 394
Wilde, G. W.	485
Wilson, Don C.	302
Wilson, James E.	348
Wilson, Stanley	437
Wilt, H. B.	485
Wood, J. E.	350
Woods, Leslie D.	137, 186
Wyant, Leroy	187, 224
Wyant, H. Wilfred	89

Y

Young, Henry S.	486
Young, W. R.	485

Z

Zange, W. H.	485
Zahnen, J. P.	187, 301

[Illustrated articles are indicated thus*]