

Thirty-Second Volume—From January, 1939, to December, 1939

General Index

{Illustrated articles are indicated thus* Editorials are indicated thus†}

A

A. & H. Corporation:
 Test Terminal..... *455

Accidents:
 Bureau of Safety annual report for June 30, 1938..... 88
 Bureau of Statistics, Interstate Commerce Commission annual statement of crossing accidents in 1938..... 403
 C. B. & Q. freight trains collide at Old Monroe, Mo..... *675
 Decrease at grade crossings..... 565
 D. & R. G. W. and A. T. & S. F. trains collide at Denver..... 513
 Derailment caused by rock slide on L. & N. near Sinks, Ky..... 600
 Derailment on Southern at Paint Rock, N. C..... 288
 Derailment on U. P. at Chard, Wash..... 288
 I. C. C. report for September, 1938..... 47
 Landslide causes derailment on M. St. P. & S. St. M. near Osceola, Wis..... 606
 Landslide derails passenger train on D. S. S. & A. near Michigamme, Mich..... 500
 Rock derails freight train on I. C. near Robbs Spur, Ill..... 502
 S. A. L.-A. C. L. at crossing protected by gates..... 41

Air Supply:
 Compressed..... 682

Alarms:
 Low air and voltage indicator..... *454

A-C. Primary:
 System on the N. Y. C. & St. L..... *656

Alton:
 Petition denied..... 226

American Association of Railroad Superintendents:
 Action at approach signal..... 504
 American Steel & Wire Company:
 Bonds, mechanically-applied rail head..... *173
 Bonds, tapered head terminal..... *182

Anaconda Wire & Cable Company:
 Booklet—ground rods and ground wire clamps..... 218

Applications:
 For signaling changes..... 52, 104, 196, 248, 298, 353, 408, 460, 518, 572, 622, 684
 R. S. & I.—I. C. C..... 622

Aspects:
 Track turnouts and signal..... †557

Association of American Railroads:
 Signal Section annual meeting..... 47, 103
 Signal Section, report of annual meeting..... *161
 Standard code revised..... 103
 Telegraph and telephone annual session, report on..... 283
 Telegraph and Telephone Section meeting..... 103, 246

Associations:
 Consolidation of exhibits..... 195

Atchison, Topeka & Santa Fe:
 Crossing protection modernized..... *281
 Mission tower interlocking at Los Angeles..... *388
 Train collides with "Scenic Limited" of Denver & Rio Grande Western..... 513

Atlanta Terminal:
 Contract with G. R. S. Co. covering material for two interlocking plants..... 683

Atlantic Coast Line:
 Accident at crossing with S. A. L..... 41

Awards:
 Advertising, to U. S. & S. Co..... 683

B

Baltimore & Ohio:
 Petition denied..... 226

Batteries:
 A.-C. primary on Nickel Plate..... *657
 Charger, self-regulating..... *559
 Device for filling..... *42
 Re-newing, procedure in..... 562

Battery charger:
 Self-regulating..... *559

Best Railway of Chicago:
 Electric switch heater units installed at Clearing yard..... *33

Biddle Company, James G.:
 Issues Bulletin 1600..... 353

Issues bulletin describing improvement in Jagabi Sliding-Contact Rheostats..... 520

Bitumeter:
 Measures distance on Wabash..... *236

Bonds:
 Rail head, mechanically-applied..... *173
 Rail, recent developments in..... *91
 Tapered head terminal..... *182
 Wire bender..... *96

Boston & Maine:
 Construction, over new Piscataqua River bridge..... 620

Bridges:
 Drag detectors on M. P..... *935
 Protecting..... *293
 St. Louis Municipal signaling..... *595

Bureau of Railway Signaling Economics:
 Discontinued December 31, 1938..... 47
 Gives library to Signal Section..... 103

Byers Company, A. M.:
 Booklet—Welding of Wrought Iron..... 248
 Catalog of tubular products..... 104
 Issues revised edition of handbook, "Wrought Iron"..... 690

C

Cable:
 Locating partial grounds..... *99
 Made-up and manufactured..... 345
 Painting..... 509

Canadian Pacific:
 Crossing protection at Chatham, Ont..... 441

Car Retarders:
 Power supply at De Witt yard on N. Y. C..... *501
 Repair program on Burlington..... *438

Cases:
 Instrument false back..... 618

Cells:
 Edison primary, 50th anniversary..... *494
 Improved dry..... *185
 Primary, improvement in..... 182

Centralized Traffic Control:
 C. R. I. & P. installs at Albert Lea, Minn..... *80
 Installed on S. P. at San Jose, Cal..... *490

Central Railroad of New Jersey:
 Route interlocking at Elizabethport, N. J..... *189

Chicago, Burlington & Quincy:
 Accident due to false clear at Old Monroe, Mo..... *675
 Car retarder repair program at Galesburg, Ill..... *438
 Semaphores replaced with color-lights..... *25

Chicago, Indianapolis & Louisville:
 Gates installed at Dyer, Ind..... *444

Chicago, Milwaukee, St. Paul & Pacific:
 Gates to replace mechanical plant at Spencer, Iowa..... 403
 Utilizes teletype..... *497

Chicago, Rock Island & Pacific:
 Application assigned for hearing..... 47
 Automatic cut-outs at automatic interlocking at Ottawa, Ill..... *548
 C.T.C. and automatic signals at Albert Lea, Minn..... *80
 Construction..... 195
 I. C. C. approves automatic interlocking to replace mechanical plant..... 39

Circuits:
 Clevis assemblies insulated..... *559
 Improving shunting of track..... 615
 Safety and design of signal..... *607
 Testing railway..... *343
 Track, checking from a motor car..... *289

Cleveland, Cincinnati, Chicago & St. Louis:
 Application assigned for hearing..... 47
 Derails to be removed at Claypool, Ind..... 404
 Removal of derails approved at Indianapolis, Ind..... 403
 Signaling application hearing re-assigned..... 108

Clevis Assemblies:
 Insulated, O.-B..... *559

Collins Oil & Manufacturing Company, Inc.:
 Succeeds Maloney Oil & Manufacturing Company..... 104

Communication Systems:
 Discussed by W. S. E..... 103

Concrete:
 Mixing during cold weather..... 44

Construction:
 Cab signals on U. P. locomotives..... 351
 C. R. I. & P. installs color-light automatic block signals..... 195
 St. L.-S. F. installs automatic block signaling..... 297
 Signaling decreased in 1938..... *19

Contact Cleaner:
 Finger spring..... *614

Conventions:
 N. R. A. A. annual exhibit..... 47
 Signal Section annual meeting..... 47, 103
 Signal Section, report of annual meeting..... *161
 Telegraph & Telephone section meeting..... 103, 246
 Telegraph & Telephone annual session, report on..... 283

Copperweld Steel Co.:
 Issues bulletin describing moltenwelding copper to steel..... 572
 Grinder..... *175
 Grounding connection..... *184
 Ground rod, sectional..... *183

Copper Wire:
 Cleaning..... 454

Crossing Protection:
 A. T. & S. F. modernizes..... *281
 Canadian Pacific at Chatham, Ont..... *441
 Florida East Coast..... *377
 For a town..... *1458
 Gates on Monon..... *444
 Highway crossing signals on the Reading in Delaware..... *544
 Interconnection of train signals..... *1613
 Manual control..... *441
 Part-time manual control of..... *678
 Railroad can purchase and install protection paid for by Federal funds..... 403
 Ten automatic gates installed on one street on Pullman..... *601
 Today's problem..... †508

Crossings:
 Determining angle at which highways cross tracks..... *290
 Movable-point, installed by M-K-T..... *280

Crossing Signals:
 See Crossing Protection

D

Delaware & Hudson:
 Spring switch replaces interlocking at Moosic tower..... *495

Denver & Rio Grande Western:
 Train collides with "Navajo" of Atchison, Topeka & Santa Fe..... 513

Depth gage:
 For small drills..... *454

Derails:
 Inside or outside the fouling point?..... 98
 Removal approved at Indianapolis, Ind..... 403
 Southern, I. C. C. permits removal..... 340
 To be removed on Big Four at Claypool, Ind..... 404

Detectors:
 Drag, protect bridges on M. P..... *335
 Dragging equipment, mounting..... 347
 Fence control..... 346
 Special aspects for..... †342

Drag Detectors:
 Bridges protected on M. P..... *335

Drills:
 Accurate grinding..... 288

Duluth, South Shore & Atlantic:
 Derailed by landslide near Michigamme, Mich..... 500

E

Edison, Thomas A., Inc.:
 Improved dry cell..... *185
 50th anniversary of primary cells..... *494
 Primary cells, improvement in..... 182

Editorial Comment:
 A Review of 1938 and a Glance Into 1939..... †40
 A Signal Shopping Policy..... †287
 C. T. C. on Multiple Track..... †287
 Crossing Protection for a Town..... †453
 Interconnection of Train Signals and Crossing Protection..... †613

Intermediate Signals and Approach Aspects 4612
 Is Quick-Acting Needed? 4237
 Problem of Medium Speed 4453
 Quick-Detachable Equipment 4237
 Signaling Regulations 4396
 Special Aspects for Detectors 4342
 Special Signal Detector Devices 4172
 Supervision in the Future 494
 Test and Inspection Report Forms 4676
 Today's Crossing Protection Problem 4605
 Track Turnouts and Signal Aspects 4557
 Electric Lights:
 Recording burning time 4238
 Equipment Detectors:
 Dragging, mounting 4347
 Drag, on the M. P. 4335
 Special aspects for 4342
 Erie:
 Electric interlocking installed at Rutherford Junction, N. J. 428
 Exhibits:
 Consolidation of 4195

F

Fansteel Metallurgical Corporation:
 Rectifier, voltage-stabilized 4178
 Transformer, voltage-stabilizing 4184
 Fence Control:
 Detector 4400
 Fences:
 Detector, on S. P. 4155
 Finger Spring:
 Cleaner 4614
 Flood Levels:
 Detecting 4561
 Floodlights:
 Approach control 4507
 Florida East Coast:
 Crossing signals 4377
 Focus:
 Color light signal 4560

G

Gates:
 Automatic on I. C. 4338
 Highway crossing mechanism 4185
 Installed on Chicago, Indianapolis & Louisville at Dyer, Ind. 4444
 Snubber, installed on Pennsylvania 4499
 Ten automatic gates on one street on Pullman 4601
 To replace mechanical plant 4403
 General Electric Co.:
 Battery charger, self-regulating 4559
 Booklet on cable joints 452
 Bulletin on magnet wire 4104
 General Railway Signal Company:
 Contracts Atlanta Terminal for materials for two interlocking plants 4638
 Issues Bulletin No. 173 concerning signaling on San Francisco-Oakland Bay Bridge 4520
 Relay, d-c, time-element 4174
 Resistor, adjustable 4174
 Sign, prismo beaded 4181
 Switch machine controller, quick-detachable 4181
 Test box, crossing signals 4184
 Goodrich Company, B. F.:
 Issues four-page catalog on its Acid-seal paints 4690
 Ground Rods:
 Sectional 4183
 Grounds:
 Locating partial 499

I

Illinois Central:
 Application denied 435
 Derailed by rock near Robbs, Spur, Ill. 4502
 Inspecting and testing signaling 4668
 Installs automatic gates 4338
 Train control plea denied 4195
 Train control plea renewed 4103
 Inductive disturbances:
 To telegraph circuits 4447
 Ink:
 Permanent, for glass, porcelain or china 4455
 Institution of Railway Signal Engineers:
 Meetings 4246
 Instrument cases:
 False back 4618
 Instruments:
 Bitometer measures distances 4236
 Grounder, Copperweld 4175
 Rectifier, voltage-stabilized 4178
 Resistor, adjustable 4174
 Sectional ground rod 4183
 Switch circuit controller rods, fittings for 4177
 Switch machine controller, quick-detachable 4181
 Vibro-Meg 4173
 Insulating Tape:
 Used in cutting glass 4507
 Insulation:
 Grass grows through wire 4293
 Ozone and moisture-resisting compound, U. S. Rubber Co. 4104
 Testing 4293
 Interlocking:
 Automatic cut-outs on Rock Island at Ottawa, Ill. 4548

Automatic plant installed on the St. Louis-San Francisco between Kansas City, Mo. and Memphis, Tenn. 4487
 C. R. I. & P. application to install automatic, approved by I. C. C. 439
 Electric, installed by Erie at Rutherford Junction, N. J. 428
 Electric, installed by New Haven at Bridgeport, Conn. 489
 Installed on S. P. at San Jose, Cal. 4490
 L. S. Angeles Union Passenger terminal Mission tower at Los Angeles 4388
 Pennsylvania at New York World's Fair 4485
 Relay, 230 routes on L. & N. E. at Hull, England 4555
 Relay, on the S. P. at Lathrop, Cal. 4541
 Route, on C. R. R. of N. J. at Elizabethport, N. J. 4139
 San Francisco-Oakland Bay Bridge 4148

Interstate Commerce Commission:
 Annual statistics on signaling 4506
 Appointments 4351
 Bureau of Safety, action at approach signal 4504
 Bureau of Safety, annual report for June 30, 1938 488
 Bureau of Safety, inspectors territorial assignments 4565
 Bureau of Statistics, statement of crossing accidents in 1938 4408
 C. C. C. & St. L. application for hearing 447
 C. R. I. & P. application assigned for hearing 447
 C. R. I. & P. installation of automatic interlocking approved 439
 Derails to be removed on Big Four at Claypool, Ind. 4404
 Gates to replace mechanical plant on C. M. St. P. & P. 4408
 I. C. application denied 485
 I. C. train control plea denied 4195
 Permits removal of derails on N. Y. C. 4286
 Permits removal of derails on Southern 4340
 Removal of derails approved at Indianapolis, Ind. 4408
 R. S. & I. applications for modifications 4622
 Rules, standards and instructions for signaling 4325
 Iowa State Highway Commission:
 Awards contracts for large highway crossing signal program 4103

K

Kansas City Terminal:
 Construction 4404
 Keys:
 Spring arrangement for 442
 Kinks:
 Approach control of floodlights 4507
 Bird stop for searchlight signal 4342
 Cleaning copper wire 4454
 Cleaning motor car gasoline 4507
 Color light signal focus 4560
 Compressed air supply 4682
 Depth gage for small drills 4454
 Electric lights, recording burning time 4238
 Electric timer 4614
 Filling batteries 4614
 Finger spring cleaner 4614
 Grade crossings, determining angle of intersection 4290
 Handling line wires 4560
 Handy tool 442
 Holder for screw-driver 4397
 Improving motor car starting 4397
 Insulating tape used in cutting glass 4507
 Jam nut wrench 4397
 Keys, spring arrangement for 442
 Light-weight portable platforms 4497
 Low air and voltage alarm 4454
 Miniature test lamp 4560
 Motor cars, controlling 4238
 Motor-car mirror 4614
 Motor cars, mixing fuel 4238
 Motor car windshield 4228
 Obtaining contact with test clips 4397
 Pipe, jacking 4289
 Power-off indicator 4397
 Power safety 496
 Relays, cleaning small bearings 496
 Relays, obtaining release values of d-c 4289
 Sandpaper for relay contacts 4238
 Testing power switches 4682
 Testing railway circuits 4343
 Track circuits, checking from a motor car 4289
 Universal bond wire bender 496
 Windshield for motor car 442
 Wrench for lightning arrester check nuts 4507

L

Lamps:
 Arm, for crossing protection gates 4444
 Electric, for semaphore signals 4227
 Electric, recording burning time 4238
 Power on motor cars 4239
 Test, miniature 4560
 Landslide:
 M. St. P. & S. Ste. M. near Osceola, Wis. 4606

Leeds & Northrup Co:
 Announces catalog describing improved Type U Test Set 408
 Lehigh Valley:
 Spring switches installed from P. & L. Jct., N. Y. to Stafford 4653
 Level Indicators: 4561
 Flood 4561
 Lightning Arresters:
 Tests of 4679
 Wrench for check nuts 4507
 Lipman Engineering Co.:
 Brochure describing high-speed photoelectric counting equipment 4408
 London & North Eastern:
 Construction 4520
 Relay interlocking with 230 routes at Hull, England 4555
 Los Angeles Union Passenger terminal:
 Interlocking 4380
 Mission Tower interlocking at Los Angeles 4388
 Louisville & Nashville:
 Construction 4460
 Derailment near Sinks, Ky. by rock slide 4600
 Electric lights for semaphores 4227
 Placed order with U. S. & S. Co. for material for remote control of functions at TJ tower, Louisville, Ky. 4683

M

Medium Speed:
 Problem of 4453
 Meters:
 D-c, relays, obtaining release values of 4289
 Minneapolis, St. Paul & Sault St. Marie:
 Landslide derailment near Osceola, Wis. 4606
 Mirrors:
 Motor-cars 4614
 Missouri-Kansas-Texas:
 Crossing, improved movable-point 4280
 Missouri Pacific:
 Automatic interlocking between Kansas City, Mo. and Memphis, Tenn. 4487
 Drag detectors protect bridges 4335
 Ordered by State Public Service Commission to install interlocking plant at St. Louis 4103
 Missouri Public Service Commission:
 Orders M. P. and Frisco to install interlocking plant at St. Louis 4103
 Monon:
 Gates installed at Dyer, Ind. 4444
 Motor Cars:
 Cleaning gasoline 4507
 Controlling 4238
 Improving starting 4397
 Lamp power 4239
 Mirror 4614
 Mixing fuel 4238
 Track circuits, checking from 4289
 Windshield 4228

N

National Railway Appliances Association:
 Annual exhibit 47
 New Devices:
 Battery charger, self-regulating 4559
 Bonds, rail head, A. S. & W. 4173
 Bonds, tapered head terminal, A. S. & W. 4182
 Clevis assemblies, insulated, O. B. 4559
 Dry cell, improved, Edison 4185
 Gate mechanism, W. R. R. S. 4185
 Grounder, Copperweld 4175
 Grounding connection, Copperweld 4184
 Ground rod, sectional, Copperweld 4183
 Permanent ink for glass, porcelain or china 4455
 Plug connector for searchlight signals, Union 4174
 Primary cells, improvements in, Edison 4182
 Rectifier, voltage-stabilized, Fansteel 4178
 Relay, d-c, time-element, G. R. S. 4174
 Relay, improved flasher, Union 4182
 Relays, plug-in, Union 4175
 Resistor, adjustable, G. R. S. 4174
 Sign, prismo beaded, G. R. S. 4181
 Signal, focusing crossing, W. R. R. S. 4183
 Signal, improved searchlight, Union 4179
 Switch circuit controller rods, fittings for, Union 4177
 Switch machine controller, quick-detachable, G. R. S. 4181
 Test box, crossing signals, G. R. S. 4184
 Testing sets, W. R. R. S. 4178
 Test terminal, A. & H. 4455
 Transformer, Union 4185
 Transformer, voltage-stabilizing, Fansteel 4184
 Twinsulation tape 4559
 Vibro-Test, W. R. R. S. 4173
 New York Central:
 Installs power supply for retarders 4501
 I. C. C. permits removal of derails 4286
 New York, Chicago & St. Louis:
 A-c primary system 4656
 New York, New Haven & Hartford:
 Interlocking, electric, at Bridgeport, Conn. 489

New York World's Fair: Signaling Pennsylvania to.....	*435	Signal Indication: Operation on single track	*44	Test clips: Obtaining contact with.....	*397
Norfolk & Western: Remote control at Devon, W. Va.....	*36	Signaling: Applications for changes 52, 104, 196, 298, 353, 408, 460, 518, 572, 622. Cab, San Francisco-Oakland Bay Bridge.....	248 684 *274	Testing: Articles on.....	502
O					
Ohio Brass Company: Bonding, recent developments in rail... Change of address of Chicago office... Clevis assemblies, insulated..... Issued bulletin entitled "Lightning protection at Lightning Speed with O-B Control Gaps".....	*91 52 *559 460	Construction decreased in 1938..... For Army-Navy game on Pennsylvan- ia.....	*19 *547	Forms for reporting inspections and tests.....	502 *682
Okonite Company: Booklet on Okonite insulation..... Establishes additional district office.....	353 353	Four-indication, problems of..... Hearings on applications for changes. Inspections and tests on the Southern. I. C. C. statistics.....	239 246 506	Power switches.....	676
Open Forum: Drills, accurate grinding of.....	288	Inspections and tests on the Southern. I. C. C. statistics.....	*435 *396	Portable field apparatus.....	*232
P					
Padlocks: Keeping moisture out of.....	679	Regulations..... Rules, standards and instructions, I. C. C.....	*325 *595 *673	Test Lamp: Miniature.....	*560
Painting: Cable.....	509	St. Louis Municipal Bridge..... Selenium rectifier for..... Standard code revised..... Testing and inspecting on the I. C. Trains directed by Signal Indication at San Jose, Cal. on S. P..... Train operation speeded up with..... Tunnels on Pennsylvania.....	*490 223 *435	Tests: Inspecting and testing signaling on the I. C.....	*668 679 *660
Paris Metropolitan: Signal aspects.....	513	Automatic, installed by Rock Island at Albert Lea, Minn.....	*80	Lightning arrestors.....	679
Pennsylvania: Signaling for Army-Navy game..... Signaling to New York World's Fair. Snubber gates installed.....	*547 *435 *499	Bird stop for searchlight..... Color light focus..... Crossing on Florida East Coast..... Crossing protection and inter-connec- tion of train.....	*84 560 *377 *613	Signaling inspections on the Southern Pennsylvania to New York World's Fair.....	*660
Pipe: Jacking.....	*289	Crossing, test box..... Focusing type lamp bracket..... Four-aspect automatics, controlling..... Highway crossing on the Reading in Delaware.....	*184 *183 *399 *644	Test Terminal: A. & H. Corporation.....	*455
Platforms: Light-weight portable.....	*97	Intermediate and approach aspects..... Iowa State Highway Commission awards contracts..... Light as train-order.....	*612 103 *100	Timer: Electric.....	*614
Power-off Indicator: Circuit for.....	*397	Maintenance, light-weight portable platforms.....	*97	Tools: Drills, accurate grinding of..... Useful small wrench.....	288 *42
Power Supply: For retarders on N. Y. C.....	*501	Paris Metropolitan aspects..... Phantom indications in color-light in Australia.....	513 *86	Track Circuits: Connection in electrified territory..... Improving shunting of.....	457 615
Pullman: Ten automatic gates installed on one street.....	*601	Remote control saves train stops on U. P.....	*229	Track Relays: Release time.....	456
Pyle-National Company: Issues two new bulletins.....	353	Searchlight, plug connector for..... Searchlight, Union..... Semaphore, electric lights for..... Semaphores replaced with color-lights on Burlington.....	*174 *179 *227 *25	Trade Publications: Anaconda—ground rods and ground wire clamps.....	248
R					
Railroad Operation and Railway Signaling: *45, *100, *186, *240, *294, *348, *401, *510, *563, *618.....	*458 *680	Testing automatic block controls..... Unusual trouble.....	457 509	James G. Biddle Co. issues a bulletin describing improvement in Jagabi Sliding-Contact Rheostats.....	520
Reading: Highway crossing signals in Delaware	*544	Signs: Prismo beaded.....	*181	James G. Biddle Co.—six instruments.....	353
Rectifiers: Selenium for signaling..... Voltage-stabilized.....	*673 *178	Simplex Wire & Cable Company: Booklet on rubber insulation for wires and cables.....	52	Byers catalog on tubular products..... Byers revised edition of handbook "Wrought Iron".....	104 690
Relays: Cleaning small bearings..... Contact pitting..... D-c., obtaining release values of..... D-c. time-element, G. R. S..... Distribution of shopping charges..... Electric timer..... Improved flasher..... Plug-in, Union..... Portable field testing apparatus..... Sandpaper for contacts..... Shopping charges..... Track, release time.....	96 *398 *289 *174 615 *614 182 175 *232 *238 347 508	Spring Switches: Testing oil-buffer.....	99	Byers—Welding of Wrought Iron..... Copperweld Steel Co. issues bulletin describing molten-welding copper to steel.....	248 690
Remote Control: N. & W. installs at Devon, W. Va..... St. L. S. W. installs at Tyler, Tex..... Saves train stops on U. P..... U. P. installs at Granger, Wyo.....	*36 *269 *229 *77	Snubber gates: Pennsylvania installs.....	*499	G. E. cable joints..... G. E. magnet wire..... G. R. S. issues bulletin No. 173 con- cerning signaling on San Fran- cisco-Oakland Bay Bridge.....	52 104 520
Repair Programs: Car retarder on Burlington.....	*439	Southern: Derailment at Paint Rock, N. C..... Derails, I. C. C. permits removal..... Signaling inspections and tests.....	288 340 *660	B. F. Goodrich Company issued four- page catalog on its Acidseal paints.....	690
Rock Detectors: Protection on Western Pacific.....	*333	Southern Pacific: Detector fences..... Relay interlocking at Lathrop, Cal..... Trains directed by signal indications at San Jose, Cal.....	*155 *541 *490	Leeds & Northrup Co., announces catalog describing improved Type U Test Set.....	408
Rock Slides: Derailment on L. & N. near Sinks, Ky.	600	Spring Switches: Installed on L. V. from P. & L. Jet. to Stafford.....	*653 *400	Lipman Engineering Co., brochure de- scribing high-speed photo-electric counting equipment.....	408
Rules, Standards & Instructions, I. C. C.: Applications for modifications.....	622	Replacing mechanisms..... Replaces an interlocking at Moosic tower on D. & H.....	*495 *291	Ohio Brass Co. Bulletin 680-H.....	460
S					
St. Louis Municipal Bridge: Signaling.....	*595	Testing.....		Okonite Company booklet on insula- tion.....	353
St. Louis-San Francisco: Automatic interlocking between Kan- sas City, Mo. and Memphis, Tenn..... Construction, Holdenville, Okla..... Construction, Tower Grove, Mo..... Ordered by Missouri public service commission to install interlocking plant at St. Louis.....	*487 297 565 565 103	Sticht & Company, Herman H.: Booklet on megohmmeter for insula- tion testing.....	52	Pyle-National Company—heavy duty conduit fittings, and Pylets.....	353
St. Louis Southwestern: Remote control at Tyler, Tex.....	*269	Switches: Spring, replaces an interlocking at Moosic tower on D. & H..... Testing power.....	*495 *682	Simplex rubber insulation for wires and cables.....	52
San Francisco-Oakland Bay Bridge: Cab signaling and train control..... Interlocking plants..... Signaling and interlocking.....	*274 *215 *148	Switch Heaters: Electric, Belt Railway installs 154.....	*83	Sticht Co. megohmmeter for insulation testing.....	52
Screens: Cleaning ventilator.....	679	Switch Machines: Controller, quick-detachable.....	*181	U. S. & S. Co.—freight classification yards.....	248
Screw-driver: Holder for.....	*397	Tape: U. S. Twinsulation.....	559	U. S. Rubber Co. insulating compound Westinghouse heating units.....	104 52
Seaboard Air Line: Accident at crossing with A. C. L.....	41	Telegraph circuits: Inductive disturbances to.....	*447	Train Control: Automatic, San Francisco-Oakland Bay Bridge.....	*274
Shopping charges: Relay.....	400	Teletype: Utilized by Milwaukee between Chica- go, St. Paul, Minn., and Minne- apolis, via La Crosse, Wis.....	*497	Train Operation: Signal indication on single track..... Speeded up with signaling.....	*44 223
Shunting: Improving of track circuits.....	615	T			
Signal Appliance Association: New officers elected at annual meeting	172	Statistics: Bureau of Safety annual report for June 30, 1938.....	88	Transformers: Power safety in replacement..... Voltage W-5..... Voltage-stabilizing.....	*96 *185 *184
Signal Aspects: Track turnouts and.....	*557	I. C. C. report on September accidents Signaling construction decreased in 1938.....	*19	Tunnels: Signaling on Pennsylvania.....	*435
Signal Circuits: Safety and design of.....	607	Stewart Research Laboratory: Permanent ink for glass, porcelain or china.....	455	U	

Bitumeter measures distances.....	*236	Detector fence control.....	346, 400	Signaling, problems of four-indication	239
Water Level:		Grass grows through wire insulation....	*293	Signals, unusual trouble.....	*43, 240, 509
Indicators.....	*561	Improving shunting of track circuits.....	615	Spring switches, testing.....	*291, 99
Welding:		Insulation, testing.....	*293	Testing automatic signal controls.....	457
Car retarder repairs.....	*438	Keeping moisture out of padlocks.....	679	Tests of lightning arresters.....	679
Western Pacific:		Light signals as train-order signals.....	*100	Track circuit connection in electrified	
Rock detector protection.....	*333	Locating partial grounds.....	*99	territory.....	457
Western Railroad Supply Company:		Location of derails.....	98	Track relay release time.....	456, 508
Crossing gate mechanism.....	*185	Made-up and manufactured cable.....	345	Who's Who in Railroading.....	677
Signal, focusing crossing.....	*183	Motor car lamp power.....	239	Windshields:	
Testing sets.....	*178	Mounting dragging equipment detec-		Motor car.....	*42
Vibro-Meg.....	*173	tors.....	347	Wire:	
Western Society of Engineers:		Operation by signal indication on		Line, handling.....	*560
Train communication discussed.....	103	single track.....	*44	Magnet.....	104
Westinghouse Electric & Manufacturing Co.:		Painting cable.....	509	Wire Bender:	
Booklet on heating units.....	52	Part-time manual control of crossing		Universal bond.....	*96
What's the Answer:		protection.....	*678	Wire Insulation:	
Bridges, protecting.....	*293	Procedure in renewing batteries.....	562	Grass grows through.....	*293
Cleaning ventilator screens.....	679	Railroad operation and railway sig-		Wrench:	
Cold weather concrete mixing.....	44	naling *45, *100, *186, *240, *294,		For lightning arrester check nuts.....	*507
Contact pitting.....	*398*401, *458, *510, *563, *618,		Handy tool.....	*42
Controlling four-aspect automatics.....	*399	Relay shopping charges.....	346, 400,	Jam nut.....	*397
		Repairing spring switch mechanisms..	*400		

Personal Mention

[Photographs are indicated thus*. Obituaries are indicated thus†]

Anderson, Ernest W.....	684	Green, J. A.....	297	Patterson, John C.....	246
Anderson, S. A.....	460	Green, R. E.....	47	Patterson, William J.....	460, *613
Andres, Matthew A.....	104	Griffiths, Frederick J.....	684	Payne, R. D.....	684
Austin, L.....	297	Groom, Thomas A.....	248	Post, Fred.....	*48
Auth, Eugene F.....	248	Grubbs, T. S.....	*1298	Price, W. F.....	460, *613
Ayer, John Jr.....	514	Gulick, John C.....	684	Pry, Edward B.....	104
Bartlett, J. L.....	246	Hamilton, J. P.....	566	Pugh, J. M.....	*352
Beck, G. E.....	*196	Hankison, W. C.....	684	Ramsey, T. B.....	514, †621
Belvin, Morton Thomas.....	621	Hanson, E. P.....	460, 513,	Reed, Philip D.....	684
Bender, F. W.....	404	Hawley, James S.....	*620	Renshaw, A. H.....	†404
Benner, T. A.....	684	Henderson, L. J.....	684	Riley, George R.....	*566
Biggers, J. W.....	621, 684	Hendrie, R. A.....	352	Rowe, C. E.....	246
Biggers, Roy.....	460	Higginbottom, Samuel B.....	241	Ryan, F. J.....	*352
Branberg, J. V.....	514	Hoffman, Clarence W.....	404	St. Clair, Edwin K.....	248
Brewster, T. P.....	48, 104	Holmberg, R. F.....	514, 566	Salmonson, W. G.....	297, 351
Bryant, James L.....	566	Iliff, R. M.....	104	Sanford, Wood.....	570
Burgin, E. A.....	*352, 518, 570	Inwood, T. G.....	246	Schubert, J. H.....	684
Burgin, J. A.....	48, *104	Irvin, Percy J.....	248	Scott, Charles F.....	103, 570
Busey, J. C.....	297	Jamieson, W. F.....	460	Sellick, S. G.....	297
Callender, Sir Thomas Octavius.....	†*52	Jennison, William.....	148	Simmons, Donald M.....	404
Cameron, Fred. C.....	570, †622	Johnson, A. H.....	297, 352	Smith, David T. G.....	†298
Cassidy, Maurice.....	47	Johnson, B. N.....	570	Smith, E. E.....	460
Chace, H. C.....	48, 104	Johnson, R. H.....	570	Smith, Raymond Wesley.....	351
Chaney, B. N.....	297	Jones, Chester.....	246	Smith, T. A.....	514, *570
Clark, G. H.....	297	Kelley, P. R.....	48	Smith, T. G.....	621, 683
Clarke, John W.....	404	Kendall, Leon B.....	620	Snyder, W. A.....	621
Clement, T. B.....	*195	Keyes, Clift B.....	†52	Stickney, N. W.....	621
Collins, Walton R.....	104	Kilian, H. L.....	246, 297	Stoltz, Carl B.....	684
Coulter, Frank A.....	104	Killigrew, Daniel L.....	570	Swope, Gerard.....	684
Crawford, A. M.....	*104	Kirkland, Charles M.....	353	Thalheimer, J. J.....	684
Daake, H. A.....	195	Kirsch, John I.....	246	Thomas, P. F.....	514
Dahleiden, F. J.....	353	Kolb, E. Worth.....	†*621	Thompson, R. L.....	514, *570
Darrach, Charles B.....	248	Lefold, G. H.....	297	Tinsley, Martin M.....	104
Denney, Charles E.....	*565	Lockerby, K. M.....	*297	Todd, G. C.....	683
Dunn, Homer W.....	*513	McArdle, R. B.....	460	Tomkins, O. Scott.....	620, *621
Durland, B. M.....	*514	McKeen, Arthur H.....	*48	Travis, C. H.....	621
Eberle, H. E.....	351, 514	McQuiston, J. A.....	48	Troth, R. W.....	683
Eck, W. J.....	404, 514	Mains, F. E.....	†460	Uhr, I. A.....	683
Essman, A. L.....	*566	Manuel, W. N.....	570	Vanderpoel, W. K.....	†*621
Felton, G. C.....	297, 351	Melton, W. S.....	297, 352	Van Loon, J. T.....	621
Forgues, J. J.....	621	Metcalf, J. W.....	246	Vaughan, R. L.....	514, *566
Forrester, W. A.....	353	Miller, D. C.....	297	Wallace, Clair M.....	246
French, J. P.....	*352	Mills, Shirley N.....	*620	Walling, Edgar W., Jr.....	684
Frenzer, P. F.....	104	Mize, F. V.....	684	Weatherby, E. P.....	*161
Friedman, J. N.....	460, 514, 566	Moyer, M. E.....	620	Weltzin, C. Frederick.....	†*48
Gallon, Terrell S.....	566	Murphy, W. L.....	246	Wesson, E. G.....	514
Gensheimer, J. S.....	*161	Nelson, C. A.....	460	Wilson, Charles E.....	684
Giles, W. F. Jr.....	514, 621	Noble, Stanley E.....	*620	Winslow, C. G.....	47
Gillespie, S. E.....	*196	Olin, B. R.....	351	Wolf, H. W.....	*353
Gladhill, P. O.....	621, 688	Oppelt, J. H.....	688	Young, Owen D.....	684
Gordon, T. T.....	297			Zimmer, Horace.....	570

Index to Authors

[Illustrated articles are indicated thus*]

Abell, W.	*238	Hardwick, B. R.	*289	Phillips, E. J.	45, *100, *186, 240,
Beck, G. E.	44	Hill, E. S.	*397	*294, *350, *401, *458, *510, *563, *618,	*680
Bender, F. W.	*139	Hillig, John E.	*232	Rasch, E. A.	*42
Bentley, Frank	*42, *397, *454,	Hoffman, W. A.	*377	Reeves, E. S.	*614
615	*507	Horn, A. M.	682	Richards, D. W.	347
Birchall, J.	615	Howard, C. G.	*673	Robison, Charles K.	*399
Bobkoski, Walter	*293	Ingles, Eugene	*399	Russell, E. L.	240
Bovard, W. P.	*91	Jensen, T. J.	400	Sebring, F. C.	*238
Bradley, E. E.	99	Johnson, A. C.	*292	Shelley, G. E.	*344
Bruce, F. C.	*607	Johnson, J. A.	98	Shevis, J. A.	*96
Byrd, Earl H.	*397	Johnson, R. D.	*560	Smith, L. W.	458
Cox, Frank E.	*560	Jones, L. M.	*447	Smith, W. R.	*293
Craig, J. H.	679	Kearnton, T. H.	347	Starling, F. E.	345
43, 44, 99, 345, 457, 507, 508, *562, 618,	679	Kimpton, E.	*42	Stilwell, W. H.	44, *227
Das, S. N.	*99,	Law, Stanley W.	346	Taylor, E. S.	346
Davis, C. Ross	457	Luse, Everett B.	560	Tegeler, F. A.	509
Dick, M. H.	*616	Maxwell, C. P.	239, 616	Uhr, I. A.	347
Dower, D. W.	346	Melhuish, C. A.	*343	Ward, J.	679
Eberle, H. E.	*289,	Miller, H. J.	*96,	Washburn, G. A.	98
*614	98	Mollis, B. W.	*291	Weatherby, E. P.	98
Eck, W. J.	238	Molloy, James H.	*80,	Werthmuller, L. S.	44, 346
Eschbach, S. E.	*397	Moore, R. E.	*42	Wiegand, F. B.	239, 615
Feeney, M. J.	*397	Morgan, H. G.	347	Williams, C. R.	*678
Fisher, A. W.	456	Morrison, C. H.	348	Woolley, G. F.	*86
French, O. C.	*281,	Murdock, C. M.	*682	Workman, R. B.	*97, *228, *289, 397,
*398	*400	Noble, S. E.	400	Wyant, L.	288
Garrett, H. B.	*454	O'Connor, John	288,	Yarmack, J. E.	*673
Gault, P. M.	223	Parkinson, J. A.	99	Zane, W. F.	*25, *438, 508
Geiger, W. H.	*454	Pfasterer, G. R.	618		
Gentry, E. H.	43				
Guigue, D.	*43, 345				

