

Thirty-Fifth Volume—From January, 1942, to December, 1942

General Index

[Illustrated articles are indicated thus*. Editorials are indicated thus†]

Accidents:

At interlocking on N. Y. C. & St. L. at Edwardsville, Ill. 484
 Bureau of Safety report 93
 C. St. P. M. & O. trains collide at Savory, Minn. *272
 Crossing, on Pennsylvania *361
 Eye 326
 February statistics 272
 Grade crossing for 1941 326
 Head-end collision on Seaboard at Hypoluxo, Fla. 323
 Head-End collision Western Pacific. In C. T. C. territory on S. A. L. near Ryan, Va. *549
 Involving overlap automatic block on St. L.-S. F. at Granby, Mo. *488
 November statistics 102
 On Cleveland, Cincinnati, Chicago & St. Louis *480
 On D. & S. L. near Azure, Colo. 554
 On L. & N. near Harold, Fla. 550
 On M. P. at Perla, Ark., in C. T. C. territory 268
 On non-block territory on K. C. S. near Acorn, Ark. 693
 On Western Pacific near Antelope, Nev. 433
 Pennsylvania at Fort Wayne, Ind. *148
 St. Louis-San Francisco near Granby, Mo. 214
 Side collision of Midland Valley and Rock Island freights 91
 Statistics for December, 1941 156
 Statistics for January 214
 Summary of Iowa grade crossings 267
All-Relay Interlocking:
 Installed on Wheeling and Lake Erie at Ironville, Ohio *258
Alton & Southern:
 Construction 328
American Automatic Electric Sales Company:
 Portable telephone *633
 "Universal" Line Pole *625
American Locomotive Company:
 Construction 506
American Railway Engineering Association:
 Signal report 224
American Standards Association:
 List of American Standards for 1942 704
American Steel & Wire Co.:
 Book on rail bonds 390
 Bulletin, "Rubber is Essential to Victory—How to Conserve it in Insulated Wires and Cables" 222
Applications:
 Denied on N. P. by I. C. C. 436
Arc Welding:
 Book by W. J. Chaffee 317
Arresters:
 Improved *635
Association of American Railroads:
 Revised Signal Section chapters. 102, Signal Section Convention cancelled. Signal Section work in war *608
 T. & T. Convention 442
Atchison, Topeka & Santa Fe:
 Construction 104
Atlantic Coast Line:
 Crossing gates, Tampa, Fla. *88
 Protection at four street crossings at Wilson, N. C. *255
Australia:
 Signal blackout studies *431
Automatic Block Signaling:
 See block signaling
Automatic Electric Company:
 Awarded Navy "E" 502
Automatic Gates:
 See Gates
Automatic Interlocking:
 See Interlocking
Automatic Signaling:
 See signaling
Automatic Signals:
 See signals

B

Back-Lock Circuits:
 None for color-light distant 697
Baldwin Locomotive Works:
 Construction 158
Base of Mast Boxes:
 Size of pole 324
 Split-base and clamp type 270
Batteries:
 Dasher for mixing primary *556
Birmingham Terminal Company:
 Construction 504
Black-Out Hood:
 Baffle-hood *153
 Range of intensity *552
Blackouts:
 Signal lamps, operation of *40
 Signal studies in Australia *431
Block Signaling:
 Installed on Great Northern on St. Paul-Duluth Line *673
 Wabash installs automatics *142
Block Signals:
 Automatic, installed on National of Mexico 156
Board of Transportation of the City of New York:
 Construction 330
Bonds:
 Improved *630
Boston & Maine:
 Replaces semaphores with light signals *415
Brakes:
 Outboard shoe-type *626
Bureau of Safety:
 Report on accident at interlocking on N. Y. C. & St. L. at Edwardsville, Ill. 434
 Report of accident on Big Four at Yorktown, Ind. *430
 Report of accident on D. & S. L. near Azure, Colo. 554
 Report on accident on K. C. S. near Acorn, Ark. 693
 Report on accident on L. & N. near Harold, Fla. 550
 Report on accident on St. L.-S. F. at Granby, Mo. *488
 Report on accident on S. A. L. near Ryan, Va. *549
 Report on accident on W. P. near Antelope, Nev. 433
 Report on derailment on Pennsylvania at Fort Wayne, Ind. *148
 Report on head-end collision on Seaboard at Hypoluxo, Fla. 323
 Report on head-end collision on Western Pacific 137
Bureau of Statistics:
 1941 grade crossing accidents 326

C

Cab-Signaling:
 Equipment for *631
Cables:
 Guide for making *381
 In signal masts or outside 553
Canadian National:
 Construction 698
Caps and Cap Gaskets:
 Protection *39
Centralized Traffic Control:
 Increases track capacity on L. & N. "Keeps 'em rolling" on D. & H. Milwaukee installs between Manilla, Iowa and Council Bluffs *247
 On Erie *189
 Pennsylvania *78
 Saves train time on section of S. P. Solves track capacity problem on Seaboard *309
 Solves war traffic problem on T. & P. Spacing of intermediates †92

Central of Georgia:
 Modern signaling for lap sidings *140
Central of New Jersey:
 New electro-pneumatic plant installed on N. Y. & L. B. *473
Central Railway of Brazil:
 Construction 158
Chicago & North Western:
 Granted deferment of interlocking changes by I. C. C. 502
Chicago, Burlington & Quincy:
 Construction 506
Chicago, Indianapolis & Louisville:
 Automatic gates installed at Lowell, Ind. *29
 Combined traffic and railroad crossing signals *548
 Modernizes automatic signaling *362
Chicago, Milwaukee, St. Paul & Pacific:
 C. T. C. signaling installed *247
 Replaces mechanical plant with all-relay interlocking *676
Chicago, Rock Island & Pacific:
 Construction 158
Chicago, St. Paul, Minneapolis & Omaha:
 Trains collide at Savage, Minn. 272
Circuit Breakers:
 For 110-volt feeds *636
Circuits:
 Series fouling *154
 Time-element *218
The City of Chicago:
 Construction 158
Cleveland, Cincinnati, Chicago & St. Louis:
 Accident at Yorktown, Ind. *480
 Automatic signals *479
Coded Carrier Control:
 Union Switch & Signal Company *625
Coded Track Circuits:
 Pennsylvania *83
 Why they can be longer 269, 500
Code Line Wires:
 Minimizing trouble if they break Pennsylvania *82
Color-Light Signals:
 Installed on M. P. to replace semaphores *366
Connections:
 Rail, as affected by running rail 268
Construction:
 During war †695
 Signaling, 1941 continued at high level *19
Controller:
 Push-pull-turn *632
Control System Time Code:
 Union Switch & Signal Company *630
Convention in Print:
 Reports of committees *610
 Signal Section work in war *608
Conventions:
 Signal Section, A.A.R. 442
 Signal Section cancelled 502
 Telegraph & Telephone Section 442
Cotters:
 Removal of rusted ones 381
Cotton Belt:
 See St. Louis Southwestern
Crossing Protection:
 At four streets on the A.C.L. at Wilson, N. C. *255
 Signal controls and train speeds †150
 Special control of signals *95
Crossing Signals:
 Special control, coded and steady energy *95
Cutter Retrievers:
 Long-Nose *631

D

Dead-Sections:
 Reduce length of *94
Defense Transportation:
 Railroad super-performance *193

Delaware & Hudson:
 C.T.C. "Keeps 'em Rolling"..... *369
 Construction 44
 Denver & Salt Lake:
 Accident near Azure, Colo..... 554
 Derrick Cars:
 For signal work..... *629
 Dim Out:
 For signal lamps by remote control..... *487
 Dim-Out Control:
 Use a resistance..... 696
 Drill Machines:
 Hole-depth stop..... *635
 New engine for..... *627

E

Editorial Comment:
 Conserving insulated wires..... †379
 Construction during war..... †695
 Crossing signal controls and train speeds..... †150
 Foundation levels..... †435
 Job on the home front..... †435
 Modern interlocking..... †695
 Scrap will help win the war..... †435, †551
 Signal construction methods during war..... †495
 Signaling materials in war time..... †209
 Signaling to be done now..... †379
 Signaling trends and developments in 1941..... †35
 Signal lights in war..... †551
 Spacing of intermediates..... †92
 Wires and cables in war time..... †495
 Electric Interlocking:
 See interlocking
 Electro-Motive Corporation:
 Construction 328, 442, 504
 Electro-Pneumatic Plant:
 Installed on N.Y. & L.B..... *473
 Erie Railroad:
 Centralized traffic control..... *189
 Exhibit in Print:
 All-electric train recorder..... *633
 Cab-signal equipment..... *631
 Circuit breaker for 110-volt feeds..... *636
 Coded carrier control..... *625
 Crossing signal test switch..... *636
 Derrick car for signal work..... *629
 Felt stripping..... 636
 Floodlight reflector..... *632
 Hole-depth stop on Mobil-drill drilling machine..... *635
 Improved arrester..... *635
 Improved bonds..... *630
 Improved rectifiers..... *637
 Long-nose cutter retriever..... *631
 Motor time relay..... *628
 New engine in drill machine..... *627
 One-man motor car..... *627
 Outboard shoe-type brake..... *626
 Plug-in a-c. relay..... *627
 Plug-in polarized relay..... *639
 Plug-in relay combinations..... *623
 Portable telephone..... *633
 Push-pull-turn controller..... *632
 Skate machine..... *639
 Speed governor..... *637
 Staggered point switch movement..... *635
 Switch locks..... *624
 Time code control system..... *630
 Tuned alternator repeater..... *638
 Type-B relays..... *640
 "Universal" line pole..... *625
 Eyes:
 Accidents to..... 326

F

Fairbanks, Morse & Company:
 One-man motor car..... *627
 Fairmont Railway Motors:
 Derrick car for signal work..... *629
 Fansteel Metallurgical Corporation:
 Improved rectifiers..... *637
 New selenium rectifiers..... *211
 Federal Works Administration:
 Apportioned funds for highway and grade crossing..... 102
 Felt Products Mfg. Co.:
 Felt stripping..... 636
 Felt Stripping:
 Fel-Pro-Thiokol..... 636
 W. H. Fenley:
 Sudden Ravings..... 694
 Flashlight Protector..... *154
 Foundation Levels..... †435
 Frost Trouble:
 Contacts and commutators in signaling apparatus, minimizing..... 41
 In outlying electric switch machines..... 696

G

Galveston, Houston & Henderson:
 Construction 158
 Gasoline Leaks:
 Stopping of..... 381
 Gates:
 Automatic, installed by Chicago, Indianapolis & Louisville..... *29
 Crossing in Tampa, Fla., Atlantic Coast Line..... *88

Installed in Decatur, Ill. by Wabash..... *319
 General Electric Company:
 Floodlight reflector..... *632
 General Railway Signal Company:
 All-electric train recorder..... *633
 Cab-signal equipment..... *631
 Motor time relay..... *628
 Outboard shoe-type brake..... *626
 Switch locks..... *624
 Type-B relays..... *640
 Grade and Highway Crossings:
 Apportioned funds for improvement..... 102
 Grade Crossings:
 Safety will hit the Axis..... 326
 Summary of accidents in Iowa..... 267
 Great Northern:
 Construction 102, 104
 Installs automatic block on St. Paul-Duluth Line..... *673
 Great Western:
 Junction signaling in England..... *266
 Ground Resistance:
 Lowered by additional ground rods..... *269
 Low resistance can be obtained..... *269
 Grounds:
 Use rail connections to test..... *381
 Gulf, Mobile & Ohio:
 Automatic interlocking installed at Bemis, Tenn..... *31
 Remote control..... *75

H

Heaters:
 Derail 39
 Highway and Grade Crossings:
 Apportioned funds for improvement..... 102
 Home Front:
 Job on the..... †435
 Hydrometer Drip Cup..... *154

I

Illinois Central:
 Automatic signal program..... *357
 Instruments:
 Testing *100
 Insulated Wires:
 Conserving..... †379
 Insulation Resistance:
 Testing..... *151
 Interlocking Changes:
 C. & N.W. granted deferment of by I.C.C..... 502
 Interlockings:
 All-relay electric installed on Milwaukee..... *676
 All-relay, installed on Wheeling & Lake Erie at Ironville, Ohio..... *258
 Automatic, installed by Gulf, Mobile & Ohio..... *31
 Automatic, installed by Missouri Pacific..... *33
 Electric, installed on Louisville & Nashville..... *194
 Modern..... †695
 Interstate Commerce Commission:
 Applications for Signal changes..... 106, 158, 222, 276, 330, 388, 446, 506, 560, 704
 Approvals of signaling changes 106, 158, 222, 276, 330, 388, 446, 506, 560
 Annual signaling statistics..... *370
 Bureau of Safety report..... 98
 Bureau of Safety report of collision on M.P. at Perla, Ark..... 263
 Bureau of Safety report on accident at Edwardsville, Ill. on NYC & St. L..... 484
 Bureau of Safety report on accident on K.C.S. near Acorn, Ark..... 693
 Bureau of Safety report on accident on L. & N. near Harold, Fla..... 550
 Bureau of Safety report on accident on St.-S.F. at Granby, Mo..... *488
 Bureau of Safety report on accident on S.A.L. near Ryan, Va..... *549
 Bureau of Safety report on W.P. near Antelope, Nev..... 433
 Bureau of Statistics report on 1941 grade crossing accidents..... 326
 December accident statistics..... 156
 Denies application to N.P. for changes..... 436
 February accident statistics..... 272
 Grants deferment of interlocking changes to C.&N.W..... 502
 January accident statistics..... 214
 November statistics..... 102
 Orders electric switch locks on L. & N..... 272
 Orders electric switch locks on M. P..... 272
 Order for Kansas City Southern..... *210
 Order for switch locks on Southern Pacific..... 268
 Iowa State Commerce Commission:
 Summary of grade crossing accidents..... 267

J

James G. Biddle Company:
 Bulletin on laboratory rheostats..... 106

K

Kansas City Southern:
 Interstate Commerce Commission order *210
 Kinks:
 Cap and gasket protection..... *39
 Dasher for mixing primary battery..... *556
 Derail heater..... *39
 Flashlight protector..... *154
 Guide for making cables..... *381
 Hammer screwdriver..... *268
 Hydrometer drip cup..... *154
 Improvement for track test shunt wires..... 39
 Locating signal trouble..... 100
 Packing remover..... *100
 Rail connections as affected by running rail..... 268
 Removing rusted cotters..... 381
 Semaphore aliner..... *556
 Series fouling circuit..... *154
 Stopping gasoline leaks..... 381
 Testing instrument..... *100
 Time-element circuits..... *213
 Use rail connections to test grounds..... *381

L

Lap Sidings:
 Modern signaling for, on C. of G..... *140
 Lehigh Valley:
 Construction 330
 Lima Locomotive Works:
 Construction 442, 558
 Line Pole:
 "Universal"..... *625
 Louisville & Nashville:
 Accident near Harold, Fla..... 550
 Construction 442, 648
 Double-track automatic signaling installed..... *531
 Installs modern plant..... *194
 I.C.C. orders electric switch locks..... 272
 Signal construction organization..... *688
 Track capacity increased by C.T.C..... *420

M

Manufacturers' Problems:
 In war, article by R. H. Weber..... *596
 Metallurgical Corp.:
 Rectifier for signal shops..... *496
 Midland Valley:
 Accident with a Rock Island freight..... 91
 Missouri Pacific:
 Automatic interlocking installed at Presley, Ark..... *33
 Collision in C.T.C. territory at Perla, Ark..... 263
 Construction 328, 330, 648
 Installs color-light signals to replace semaphores..... *366
 I.C.C. orders electric switch locks..... 272
 Motor Cars:
 Cap and gasket protection..... *39
 One man..... *627

N

Nashville, Chattanooga & St. Louis:
 Construction 648
 National of Mexico:
 Installation of automatic block signals..... 156
 National Safety Council:
 Safety awards presented..... *318
 New Books:
 Practical Arc Welding..... 317
 New Devices:
 All-electric train recorder..... *633
 Cab-signal equipment..... *631
 Circuit breaker for 110-volt feeds..... *636
 Coded carrier control..... *625
 Crossing signal test switch..... 636
 Derrick car for signal work..... *629
 Felt stripping..... 636
 Floodlight reflector..... *632
 Hole-depth stop on Mobil-drill drilling machine..... *635
 Improved arrester..... *635
 Improved bonds..... *630
 Improved rectifiers..... *637
 Long-nose cutter retriever..... *631
 Motor time relay..... *628
 New engine in drill machine..... *627
 One-man motor car..... *627
 Outboard shoe-type brake..... *626
 Plug-in a-c. relay..... *627
 Plug-in polarized relay..... *639
 Plug-in relay combinations..... *623
 Portable telephone..... *633
 Push-pull-turn controller..... *632
 Rectifier for signal shops..... *496
 Selenium rectifiers for interlocking plants..... *211
 Skate machine..... *639
 Speed governor..... *637
 Staggered point switch movement..... *635
 Switch locks..... *624

Time code control system.....*630
 Tuned alternator repeater.....*638
 Type-B relays.....*640
 "Universal" line pole.....*625
New York & Long Branch:
 New electro-pneumatic plant installed.....*478
New York, Chicago & St. Louis:
 Accident at interlocking at Edwardsville, Ill.....484
New York, New Haven & Hartford:
 Construction.....380
Norfolk Southern:
 Construction.....44
Northern Pacific:
 Application for changes denied by I.C.C.....436
 Construction.....44

O

Ohio Brass Company:
 Hole-depth stop on Mobil-drill drilling machine.....*635
 Improved bonds.....*630
 New engine in drill machine.....*627

P

Pacific Electric:
 Construction.....648
Packing Remover.....*100
Pack-Rite Machine Corporation:
 Long-nose cutter retriever.....*631
Passing Track:
 Improved facilities and signaling on P.M.....*303
Pennsylvania:
 Accident, switch thrown in front of train at Fort Wayne, Ind.....*148
 Centralized traffic control.....*78
 Coded track circuits.....*83
 Crew "Keep 'Em Rolling".....214
 Crossing accidents.....*861
 Minimizing trouble if code line wires break.....*82
 Preventing clearing of opposing semi-automatic signals.....*85
 Two-wire line controls for automatics.....*84
Pere Marquette:
 Improved passing track facilities and signaling.....*303
Poems:
 "A Tune from an Old Rail".....206
Poles:
 Treated, production of during 1941.....502
Postal Telegraph:
 Proposed merger with Western Union.....272
Practical Arc Welding:
 By W. J. Chaffee.....817
Primary Batteries:
 Dasher for mixing.....*556
Priorities:
 Higher for signaling.....386
 Railway materials.....*208
Public Belt Railroad Commission:
 Construction.....104

R

Rail Connections:
 As affected by running rail.....268
 Used to test grounds.....*381
Railroad Accessories Corporation:
 Improved arrester.....*635
Railroad Purchases:
 Increased in 1941.....214
Railroad Super-Performance:
 Defense transportation.....*193
Railway Materials:
 Priorities.....*208
Railway Salvage:
 Railroads and individuals urged to intensify scrap drives.....*546
Reading:
 Construction.....220, 222, 380
Rectifiers:
 For signal shops.....*496
 Improved.....*637
 Selenium, for interlocking plants.....*211
Reflectors:
 Floodlight.....*632
Relays:
 Motor time.....*628
 Plug-in a-c.....*627
 Plug-in combinations.....*623
 Plug-in polarized.....*639
 Repeater, important difference.....324
 Retained, various uses.....*439
 Testing a-c.....*212
 Type-B.....*640
Remote Control:
 And automatic signaling on Southern Gulf, Mobile & Ohio.....*484
Repeaters:
 Tuned alternator.....*638
Rock Island:
 Accident with a Midland Valley freight.....91

S

Safety:
 Awards presented.....*818
 Bureau of.....98
St. Louis—San Francisco:
 Accident involving overlap automatic block at Granby, Mo.....*488
 Accident near Granby, Mo.....214
St. Louis Southwestern:
 Construction.....698
 Installs signaling facilities.....*131
Scrap:
 Will help win war.....†435
 Will win war.....†561
Scrap Drives:
 Railroads and individuals urged to intensify drives.....*546
Screwdriver:
 Hammer.....*268
Seaboard Air Line:
 Accident near Ryan, Va.....*549
 C.T.C. solves track capacity problem.....*309
 Construction.....102, 504
 Head-end collision at Hypoluxo, Fla.....323
Selenium Rectifiers:
 See rectifiers
Semaphores:
 Aliner for.....*556
 Replaced by color-light signals on M. P.....*366
 Replaced by light signals on B. & M.....*415
Semi-Automatic Signals:
 Preventing the clearing of opposing Pennsylvania.....*85
Shunt Wires:
 Improvement for track test.....39
Signal Aspects:
 Blackouts, operation of lamp during.....*40
Signal Construction Organization
 On the L. & N.....*688
Signaling:
 Application for changes.....46, 106, 158, 222, 276, 380, 388, 446, 506, 560, 704
 Approvals of signaling changes.....106, 158, 222, 276, 380, 388, 446, 506, 560
 As considered by W.P.B., article by Eugene Moore.....*597
 Automatic, and remote control on Southern.....*484
 Automatic, modernized on C. I. & L.....*362
 Automatic, on I. C.....*357
 Construction continued at high level in 1941.....*19
 Construction methods during war.....†495
 Contributing to success of war rail transportation.....*138
 Dim-out control.....696
 Double-track automatic on L. & N.....*531
 For a switching track by use of switch signal.....*325
 For a switching track, one lever for two signals.....*498
 Frost on contacts and commutators, minimizing trouble.....42
 G. N. installs automatic block on St. P.-Duluth line.....*673
 Helping to win the war.....*556
 Higher priorities for.....386
 Improved passing track facilities on P.M.....*303
 Junction, on Great Western in England.....*266
 Modern, for lap sidings on C. of G.....*140
 Statistics, annual I. C. C.....*370
 To be done now.....†379
 Trends and developments in 1941.....†35
 Utilization of in war.....*599
Signaling Facilities:
 Installed by St. Louis Southwestern (Cotton Belt).....*131
Signaling Materials:
 In war time.....†209
Signal Lamps:
 Dim out for, by remote control.....*437
Signal Masts:
 Cables in or outside.....558
Signal Report:
 By American Railway Engineering Association.....224
Signals:
 Automatic, on Big Four.....*479
 Automatics installed on Wabash between Bement, Ill. and Tolono.....*142
 Black-out hood for.....*153, *552
 Black-out studies in Australia.....*431
 Color-light, installed on M. P. to replace semaphores.....*366
 Combined traffic and railroad crossing on C. I. & L.....*548
 Go to war, article by Joseph B. Eastman.....*595
 Light, replace semaphores on B. & M.....*415
 Lights in war.....†551
 Locating trouble.....100
 Preventing clearing of opposing semi-automatic.....*85
 Semaphore aliner.....*556
 Spacing of intermediates.....†92
Signal Section, A.A.R.:
 Convention cancelled.....502
 Work in war.....*608

Signal Section Chapter:
 Revised.....326
Skate-Machine:
 Pneumatically-operated.....*639
Speed Governor:
 For Diesel locomotives.....*637
Southern:
 Automatic signaling and remote control.....*484
Southern Pacific:
 C. T. C. saves train time on.....*538
 Construction.....386
 Ordered concerning switch locks.....268
Spring Switch Mechanism:
 Support not needed.....384
 Support recommended.....*384
Statistics:
 Accident, for January.....214
 December accidents.....156
 February accidents.....272
 I. C. C. annual signaling.....*370
 November accidents.....102
 Signaling construction in 1941.....*19
 Telegraph and telephone facilities increased—1941.....*26
Sudden Ravings:
 By W. H. Fenley.....694
Switch Locks:
 G. R. S. Co. Model-9A.....*624
 I. C. C. orders on S. P.....268
Switch Machines:
 Frost trouble in outlying electric.....697
Switch Movements:
 Staggered point.....*635

T

Telegraph and Telephone Facilities:
 Increased during 1941.....*26
Telegraph & Telephone Section, A.A.R.:
 Convention.....442
Telegraph Merger Bill:
 Proposed merger of Western Union and Postal Telegraph.....272
Telephones:
 Portable.....*633
Testing:
 A-c. relays.....*212
Test Switch:
 Crossing signal.....636
Texas & Pacific:
 C. T. C. solves war traffic problem.....*682
 Construction.....44, 158
Time-Element Circuits:
 See circuits
Track Capacity:
 C.T.C. solves problem on Seaboard.....*309
 Increased by C.T.C. on L. & N.....*420
Track Circuits:
 Why coded can be longer.....269, 500
Trade Publications:
 American Standards Association List of American Standards for 1942.....704
 American Steel & Wire Co. new bulletin, "Rubber is Essential to Victory—How to Conserve it in Insulated Wires and Cables.".....222
 American Steel & Wire Co. on rail bonds.....390
 The James G. Biddle Company "Jagabi Lubri-tact" laboratory rheostats.....106
Train Recorder:
 All-electric.....*633
Train Speeds:
 Crossing signal controls.....†150
Transformer Polarity:
 Determination of by lamp method.....*500
Treated Poles:
 Production of during 1941.....502
Two-Wire Line Controls, for Automatics:
 Pennsylvania.....*84

U

Union Pacific:
 Campaigns to eliminate grade crossing accidents.....326
 Construction.....386
Union Switch & Signal Company:
 Coded carrier control.....*625
 Construction.....220
 Crossing signal test switch.....636
 Plug-in a-c. relay.....*627
 Plug-in polarized relay.....*639
 Plug-in relay combinations.....*623
 Push-pull-turn controller.....*632
 Skate machine.....*639
 Speed governor.....*637
 Staggered point switch movement.....*635
 Time code control system.....*630
 Tuned alternator repeater.....*638
United States Navy:
 "E" award to Automatic Electric Co.....502

W

Wabash:
 Installs automatics.....*142
 Installs gates in Decatur, Ill.....*319
War:
 Helping to win the war.....556
 Manufacturers' problems, article by R. H. Weber.....*596

Railroad signals go to war, article by Joseph B. Eastman.....	*596	Western Union: Proposed merger with Postal Tele- graph.....	272	Retained relays, various uses.....	*439
Scrap will win war.....	†551	Westinghouse Electric & Manufacturing Co.: Circuit breaker for 110-volt feeds....	*636	Signal aspects during blackouts.....	*41
Signal lights in.....	†551	What's the Answer: Back-lock circuits.....	697	Signal black-out hood.....	*153, *552
Utilization of signaling.....	*599	Base of mast boxes.....	270, 324	Signaling for a switching track.....	*325
War Production Board: B. C. Bertram, Director of Railway Salvage speaks to Pittsburgh Ry. Club.....	*546	Cables in signal masts or outside.....	553	Signaling for a switching track, one lever for two signals.....	*494
Consideration of signaling, article by Eugene Moore.....	*597	Conserving wires and cables.....	382	Special control of crossing signals, coded and steady energy.....	*95
Higher priorities for signaling.....	386	Determining transformer polarity- lamp method.....	*500	Support for spring switch mechan- ism.....	*384
Railway materials and priorities.....	*203	Dim-out control.....	696	Testing a-c relays.....	*212
Signaling materials in war time.....	†209	Dim out for signal lamps by remote control.....	*437	Testing insulation resistance.....	*151
War Rail Transportation: Signaling contributing to success of..	*138	Frost trouble.....	696	Why coded track circuits can be longer.....	269, 500
Western Pacific: Accident near Antelope, Nev.....	433	Ground resistance, lowered by addi- tional ground rods.....	*269	Wheeling & Lake Erie: Installs all-relay interlocking at Ironville, Ohio.....	*258
Head-end collision near Sunol, Calif..	137	Minimizing frost trouble.....	42	Wires and Cables: In war time.....	†495
		Reduce length of dead-sections.....	*94	Items for consideration for conserv- ing.....	382
		Repeater relays.....	324		

Quick Reference to Feature Articles

Atlantic Coast Line.....	*88, *255	Cotton Belt See St. Louis Southwestern.....		New York & Long Branch.....	*473
Boston & Maine.....	*415	Erie Railroad.....	*189	Pennsylvania.....	*78
Central of Georgia.....	*140	Great Northern.....	*673	Pere Marquette.....	*303
Central of New Jersey.....	*473	Great Western, England.....	*266	St. Louis Southwestern.....	*181
Chicago, Indianapolis & Louisville.....	*29, *362, *548	Gulf, Mobile & Northern.....	*31	Seaboard Air Line.....	*309
Chicago, Milwaukee, St. Paul & Pacific	*247, *676	Gulf, Mobile & Ohio.....	*75	Southern.....	*484
Cleveland, Cincinnati, Chicago & St. Louis	*479	Illinois Central.....	*857	Southern Pacific.....	*538
		Louisville & Nashville.....	*194, *420, *531, *688	Texas & Pacific.....	*682
		Missouri Pacific.....	*33, *366	Wabash.....	*142, *319
				Wheeling & Lake Erie Railway.....	*258

Personal Mention

[Photographs are indicated thus*. Obituaries are indicated thus†]

Allmanky, Max I.....	*218	Elg, E. G.....	106	Hulse, H. A. Jr.....	504, *558
Ames, Axel.....	†*702	Eschbach, S. E.....	*274	Hunot, A. H.....	328
Anderson, M. F.....	156, *218	Fenley, William H.....	†*702	Hutchings, W. R.....	386
Appleby, H. A.....	*388	Follett, Waldo F.....	*442	Iba, P. W.....	504
Armistead, A. B.....	218, *274	Ford, William A.....	442	Jacobs, Wm. A.....	*444
Ayer, John Jr.....	504	Fuller, D. W.....	44	Johnson, C. H.....	648
Ayers, B. H.....	648	Gallagher, J. R.....	504	Johnson, W. C.....	328, *386
Balliet, R. H. C.....	44	Gardner, J. C.....	648	Karlet, J. G.....	218, 274
Benson, W. E.....	648, 698, *700	Garton, Charles I.....	*648	Keers, Charles B.....	*444
Beoddy, J. A.....	44, *218	Gould, J. P.....	106	Kelloway, C. J.....	*442
Binning, C. D.....	328	Grundy, C. F.....	444	Kennedy, C. E.....	328, 386, *444
Bishop, Charles E.....	†698	Hamaker, L. S.....	*328	Kocher, W. J.....	328
Blythe, George.....	328	Hammond, W. H.....	106	Lapsley, Rhea.....	106
Branberg, J. V.....	504	Hangarter, Ernest J.....	†276	Law, S. W.....	44
Brown, G. L.....	44, 104	Harris, L. T.....	650, †*702	Leach, A. B.....	106
Brown, O. H.....	504	Harris, Marshall L.....	†220	Leberknight, Dr. Charles E.....	*702
Carpenter, L. D.....	560	Hartzell, F. D.....	504	L'Heureux, L.....	106
Chatten, F. L.....	504	Healy, J. J.....	106, 386	Lofstrand, Oscar S.....	*698
Clark, Leslie.....	*274	Herring, Otis W.....	106	Lorenzen, Harry C.....	*44
Clement, T. B.....	*156	Hesser, J. M.....	218, 274	McFarland, J. E.....	504
Corcoran, J. J.....	44	Hobson, Harry.....	†*446	McGuire, Richard Rell.....	*156
Dickinson, L. D.....	444	Hobson, John S.....	†*446	McKithan, Robert B.....	648, 698, *700
Dodds, T. L.....	44	Hodgdon, C. R.....	44	Manuel, W. N.....	*504
Duffy, C. M.....	44, 558	Holm, Albert L.....	*650, 698	Margsh, R. W.....	156, *216
Durland, Benjamin Merrill.....	276, 504	Holmberg, C. R.....	504, *560	Matejshek, F. J.....	698
Eaton, B. C.....	*276	Hovey, Wm. G.....	†504	May, T. W.....	698
Ege, W. W.....	106	Howard, Carl G.....	*650	Maynard, H. A.....	*558

Melby, J. P.....	650, 698	Raasch, R. C.....	106	Stanton, H. L.....	44
Merrell, O. J.....	44, 104	Ramsay, A. Milne.....	46	Stroud, William D.....	106
Morcom, Thomas Henry.....	*†104	Ramsey, Glen.....	*650	Swenson, C. R.....	*558
Morrison, Charles Harry.....	†*388	Rathbun, H. V.....	106	Swiers, S. D.....	44, 104
Muller, J. P.....	44	Ray, W. G.....	*700	Taylor, Carl Addison.....	*272
Murphy, F. J.....	650, 698	Rees, Frank X.....	*276	Taylor, Roy E.....	442, *502
Muse, K. L.....	216	Reich, E. W.....	44	Testerman, Roy E.....	*648
Niedeck, J. A.....	328	Reilly, Albert.....	*216	Thomas, J. R.....	698
Noble, S. E.....	44, 328	Rhudy, W. H.....	*700	Towne, Harold M.....	*218
Oliphant, L. W.....	*386	Richards, D. W.....	*218	Troth, R. E.....	648
Ottoson, Harry.....	698	Rodger, G. A.....	44	Troughton, E. T.....	504, *558
Parkinson, J. A.....	*388	Ross, G. C.....	648	Trout, Geo. W.....	†*46
Peacock, Maurice.....	328	Sagen, E. R.....	44, 104	Uhr, S. L.....	648
Pearce, R. L.....	648	Sanford, Wm. T.....	446	Van Eaton, G. R.....	*328
Peeler, W. E.....	504, *560	Sauer, J. A.....	†328, †386	Vroman, James B.....	158
Pendorf, Paul G.....	46	Saunders, J. E.....	156, *216	Walters, C. E.....	504
Petrie, J. N.....	444	Scott, Thomas W.....	†46	Webb, J. S.....	*214, *444
Pfleging, F. W.....	444, †*702	Shannon, E.....	648	Wiegand, Frederick B.....	†*220
Phillips, E. J.....	328	Shapley, John J.....	*106	Wilburn, Ebbert E.....	698
Platt, E. P.....	386	Sisk, V. G.....	648, *649	Williams, George.....	328
Pugh, J. M.....	698	Smeltzer, V. O.....	648, 698, 700	Williams, M. R.....	648, 700
Puls, Roy F.....	156, *216	Sparks, John W.....	648, 698	Wilson, M.....	328
				Woodfill, C. C.....	648

Index to Authors

[Illustrated articles are indicated thus*†]

Bender, F. W.....	*473	Hillig, J. E.....	*437	Robinson, C. K.....	*151
Bentley, Frank.....	*154	Hoffman, John H.....	*39, *268	Sampson, H. C.....	*325
Bone, H. L.....	324	Jacobs, W. A.....	*381	Smith, J. W.....	696
Bound, A. F.....	*552	Jensen, C. H.....	*269	Smith, W. R.....	697
Broomfield, R. L.....	*218	Johnson, C. A.....	*384	Stevenson, Andrew.....	*208
Brown, B. O.....	*269	Kelloway, C. J.....	270	Stewart, J. J.....	*556
Corcoran, J. J.....	*608	Kimpton, E.....	268, 553, 697	Storms, W. S.....	270
Craig, J. H.....	553, 696	Lang, R.....	*151	Stradling, E. J.....	553
Eastman, Joseph B.....	*193, *595	Miller, Oscar, E.....	*154, *206	Tomme, James M. Jr.....	*100
Elliott, Charles J.....	39	Minett, R.....	*381	Walters, L. C.....	384
Fenley, W. H.....	694	Moore, Eugene.....	*597	Ward, James.....	324, *500
Garton, C. I.....	*498	Nachod, Carl P.....	*212	Weatherby, E. P.....	*153
Gilson, R. M.....	500	Parkinson, J. A.....	*384	Weber, R. H.....	*596
Gowan, Edward J.....	*100	Patton, W. L.....	*154	White, F. J.....	382
Guigue, D.....	697	Ramsey, W. A.....	39, 100	Whitehurst, W. M.....	*140
Hartman, W. N.....	384	Reichard, W. H.....	269	Willing, J. E.....	*439
Henry, R.....	*556	Rice, A. H.....	553	Woolley, George F.....	*431

